



DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/Diagonal Sed Rem Project

PRIME CONTRACTOR: MILLER CONTRACTING

TIME WORK STARTED: TIME WORK STOPPED

	•				
Year	r Montl	h	Day	Ins	pector
2003	3 11		14		rb
	Day	y of the W	<u>eek</u>		
Sat	Sun Mon	Tue	Wed	Thu	Fri
					X
		<u>Weather</u>			
•					
Clear	PC	Overcast	Fog	3	Rain
		X			
	· <u>T</u>	<u>emperatu</u>	re		
10-32	32-55	55-70	70-8	5	85+
	X				

Date

Construction Activities:	Miller Contracting on site today for the afternoon	or start dredging. Crew mobed on site or	11-13-03 staring in
	Crew started dredging at 2AM this	s morning. Crew completed filling Swar 25 at 0745. Started dredging and loadin Miller for additional information	n Island this morning ing the Sand Island at
	Dredge-Crystal Gayle	1 Supervisor 3- Dredge crew	
	Tug- Norton Bay	2- Tug crew	
	Tug-Loren M Barges, Sand Island/ Swan Island Survey Boat	2- Survey	
Miscellaneous:			
Safety/Accidents:			
Problems Encountered & Resolutions:			
Test Conducted:			
Work Rejected:			
Instructions Given to		·	
Contractor & Changes Initiated:			
Visitors to Site			

JROleva

11/19/03

Jkwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

ı	Ja	τe

	<u>M.</u> .	L King Jr.	<u>Holiday</u>		
Yea	r Mo	onth	Day	Ins	spector
200	4 I		19	г	b/KN
]	Day of the Y	Week		
Sat	Sun Mo	n Tue	Wed	Thu	Fri
	Х				
	•	Weathe	<u>•r</u>		
Clear	PC	Overcas	t Fo	g	Rain
	X				
		Temperat	<u>ure</u>		
10-32	32-55	55-70	70-	85	85+
	x				

Construction Activities:

Day Shift: 5:00AM to 1:00PM

Dredging resumed this morning at 5:19AM. Contractor continued filling the "Sand Island" (started Sunday evening). Work proceeded N. to S. in Area A to complete excavation profiles to meet the Contract. Contractor started at app. Dredge Plan sta. 4+22 (55) and removed "high spots" at app. stas. 4+64, 4+92, 5+20, 5+53.

Dredging stopped at 9:22AM to reposition the "Sand Island", and for "Crystal Gayle" maintenance.

Dredging resumed in about the same area at 10:14AM working upstream towards area B. Dredging stopped at 12:30PM for shift change.

Night Shift: 1:00PM to 9:00PM

Dredging resumed at 1:03PM. Work is proceeding S. towards Area A in the outside lane. Dredging stopped at 1:18PM. Contractor made a failed attempt to relocate the "Crystal Gayle" to location just off the 144" City SD in Area A(see Problems Encountered- below for further details).

Contractor <u>resumed</u> dredging on the outside lane between Dredge Plan sta. 6+60 and 7+80, after app. 7:00PM. Dredging continued until 9:20PM, when the crew stopped to do equipment greasing. Dredging resumed at 10:00PM, and continued with only occasional stops until after 00:30AM, when the "Norton Bay" returned with the "Swan Island". Dredging continued. By 2:45PM the Flood Tide was high enough, and the Contractor moved back into the area adjacent to the 144" SD in Area A and resumed dredging until 3:15AM, when the bucket was finally set down.

Dredge- "Crystal Gayle"

Tug- "Norton Bay"

Tug- "Loren M"

Barges "Sand Island"/ "Swan Island"

Survey Boat Crew Skiff 1- Supervisor

3- Dredge Crew


2-Tug crew

2- Survey Crew

UROLEVA 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

Page 1 of 2



Miscellaneous:	Miller surveyors on site this morning to continue mapping out dredge Area A. "Crystal Gayle"						
	pulled off the site from app. 1:30PM until app.5:30PM(see Problems Encountered-below for						
	further details). Miller Surveyors took advantage of the cleared site to run complete lines, and						
	re-survey Area A.						
Safety/Accidents:	No incidents/accidents were reported to KC by the Contractor.						
Problems Encountered &	Contractor began relocating the "Crystal Gayle" to an area (shown cross-hatched in the Dredge						
Resolutions:	Plan, sheet C-2) just off the 144" City SD in Area A after 1:30PM. The Contractor had app.						
	600 cu. yds. of material remaining to remove, and wanted to take advantage of the high tide to						
	move close to shore. During the move the Contractor lost pendant lines on both of their						
	downstream work anchors. In such event, the "Crystal Gayle" (not the Tug "Loren M") has to						
	retrieve the anchors. While the Dredge was off site, Miller used the event to re-survey Area A.						
	By the time the anchors were repaired, and the Dredge returned, the tide had already gone well						
	into ebb (low tide of -2.5 was anticipated by app. 7:20PM). Dredge resumed work after						
	7:00PM, with new survey data and instructions from Miller.						
Test Conducted:	KC lab on site this morning at 10:51AM to take water turbidity samples. KCEL decided not to						
	conduct the afternoon Ebb Tide test because of the late hour when dredging finally resumed.						
Work Rejected:							
Instructions Given to	Tom Johnson requested time extension from KC for this Night Shift to finish dredging along						
Contractor & Changes	the outside lane of A, and hit the two high spots in Area B. The Contractor needed to have the						
Initiated:	"Crystal Gayle ready at 5:00AM for the next high tide to finish at the position just off the						
	144" City SD in Area A (they missed their high tide window to move in to excavate earlier this						
	shift. See Problems Encountered- above for further details). KC granted the time extension						
	only because it was the final night dredge).						
Visitors to Site							
Equipment Used							
<u> </u>							





KING COUNTY **DEPT. OF NATURAL RESOURCES** WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Mont	h	Day	Ins	pector
2004	1	1		20	1	b/KN
		<u>Da</u>	y of the W	<u>eek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
			X			
			Weather			
				•		
Clear	P	° C	Overcast	Fo	g	Rain
		X		•	_	
	•	-	,			
		_	<u>'emperatu</u>	_		
10-32	32	2-55	55-70	70-8	35	85+
1		X				

Date

Construction Activities:	Day Shift: 5:00AM to 1:00PM					
		etting anchors and performing maintenance. Dredging				
		'SD outfall at Dredge Plan (see sheet C-2) app. sta.				
	5+30 for the "Swan Island". The dredgi	ng into "Swan Island" was started on last Night Shift.				
		reposition barge and perform maintenance.				
		+62 next to shore. Dredging stopped at \$\dplue{2}:25PM.				
:35	"Crystal Gayle" Operator came to shore Night Shift: 1:00PM to 9:00PM	to meet with Miller to go over the latest Miller survey.				
:35		nd" on the inside lanes between Dredge Plan sta. 3+00				
		yle" moved back to the outside (channel) lane to				
i i		an sta. 6+60 and 8+00 (area worked last night). At				
		upstream to Area B to complete removal of "high				
		Contractor worked at positioning the barge for the				
		gan moving up to Area B to move outside of the				
		e spud on the "Crystal Gayle" and finish the dredging.				
	Dredging stopped at 9:08PM.	, , , , , , , , , , , , , , , , , , ,				
	The Contractor used the balance of their	night work to rearrange the load on the "Swan Island",				
	and haul the barge down to Terminal 25.					
	Dredge - "Crystal Gayle"	1- Supervisor				
	Tug - "Norton Bay"	3- Dredge Crew				
	Tug -"Loren M" 2-Tug crew					
	Barges "Sand Island"/ "Swan Island" 2- Survey Crew					
	Survey Boat					
	Crew Skiff					
Miscellaneous:		ly for Vacuum Truck cleanup at Terminal 25 (per Cato,				
	Wilder).					
Safety/Accidents:	No incidents/accidents were reported to	KC by the Contractor.				

UKOLEVA 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Pate)



REPORT NUMBER: C33027C

Problems Encountered & Resolutions:	Contractor (T. Johnson) at 7:00PM that KC wanted the dredging to "stop" at 9:00PM as agreed as part of this two shift arrangement with the Contractor (per Ukwenga Oleru). At 8:20PM the dredge began the move to Area B, and drop the spuds in what Mr. Johnson claimed was open channel "outside the boundaries of the dredge area, and where he said Miller had permission to use spuds for dredging by the Port.					
Test Conducted:	KC lab on site this morning to take turbidity water samples (sample taken). KCEL on site this afternoon to take samples. KCEL cancelled testing, as the test results from the sporadic dredging would not be valid.					
Work Rejected:						
Instructions Given to Contractor & Changes Initiated:	Notified Contractor (T. Johnson) at 7:00PM that KC wanted the dredging to "stop" at 9:00PM as agreed as part of this two shift arrangement with the Contractor. Contractor continued dredging until work was complete at 9:08PM.					
Visitors to Site	Cato, Wilder; Rob Matheison (left site @5:00PM), Tom Johnson, JJM; Colin Wagoner, NOAA Consult.					
Equipment Used						





REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)

TIME WORK STARTED: TIME WORK STOPPED:


		•					
Year	-	Mont	h	Day	In:	spector	
2004		1		23		KN	
	Day of the Week						
Sat	Sun	Mon	Tue	Wed	Thu	Fri	
						Х	
			Weather	•			
				=			
Clear	P	C	Overcast	Fo	g	Rain	
			Х			Х	
<u>Temperature</u>							
10-32	32	-55	55-70		35	85+	
		X					

Date

Construction Activities:	Miller surveyors (on site at 0800hrs). JJM began the capping phase of this Contract at the site. JJM received approval to begin that phase of the contract in the form of phone calls from Ukwenga Oleru and Randy Daggett, JJM to Cameron McIntosh and this observer at relatively the same time, 1200hrs. The "ME209/ME216" working platform for the capping operation, is beginning base capping work in Area B. The platform has set out working anchors, and spuds are retracted. At app. 1400hrs, this observer rode out to the platform to verify displacement of "ME311" barge with "sand" capping material (signed Miller's form for that barge). The first drop of material was at the S. (upstream end) of Area B at 1450hrs., and first stop at 1520hrs. (about the same time KCEL got on site). Sand capping resumed after 1547hrs., and stopped again at 1610hrs. JJM is trying to work out problems with their WINOPS. Base capping continued with only occasional stops until 2000hrs.
Miscellaneous:	"Swan Island" is still waiting to be offloaded at Terminal 25.
Safety/Accidents:	No incidents/accidents were reported to KC by the Contractor.
Problems Encountered & Resolutions:	Cameron McIntosh, and Miller Surveyors were on site, and had several questions (regarding grades, materials combinations) needing clarification. The Contractor received verbal clarification during a conference call with Ukwenga Oleru, KC/CM, and Bruce McDonald (Anchor Eng.) to this Site Office at app. 1230hrs. The Contractor has agreed to follow up with written Request for Clarification to the owner ASAP.
Test Conducted:	KCEL on site at 1520hrs. to take first of the tests for turbidity levels during the capping operation. KCEL(Bob Kruger) called off the sampling because the Contractor's long work stop after app. 30min. of sand spreading, invalidated any possible test within the sampling window for this Flood Tide.
Work Rejected:	
Instructions Given to	
Contractor & Changes Initiated:	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund, Construction Inspector (Date)



Visitors to Site	RobMatheison, JJM	
Equipment Used	JJM Survey Boat "Doppler" Tender Tug "Mary Margaret" Anchor Tender "Miller 102" Sand Barge "ME311"	2 crew persons 1 supervisor
	Capping Barge/Hitachi 1800 Excav., "ME209" Capping Barge/Crane/Loader, "ME216"	3 crew persons





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)

TIME WORK STARTED: TIME WORK STOPPED:

Year	r	Mon	th	Day	Ins	spector	
2004	1	1		24	I)	K/ KN	
	Day of the Week						
Sat	Sun	Mon	Tue	Wed	Thu	Fri	
x							
			Weather	<u>r</u>			
Clear	I	PC	Overcast	Fo	g	Rain	
			X				
		1	<u> Femperati</u>	<u>ıre</u>			
10-32	32	2-55	55-70	70-	85	85+	
		X					

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM
Construction Activities:	Day Shift: 6:00AM to 2:00PM Miller surveyors already on site. JJM continued the capping phase of this Contract at the site in Area B, working overnight on barge "ME312". The "ME209/ME216" working platform for the capping operation, is continuing base capping work in Area B. JJM continued capping through last night, and started up with new shift crew this morning at app. 0600hrs. Capping work continued with occasional short stops until app. 0825hrs., and then Contractor relocated further downstream. At app. 0900hrs, JJM emptied barge "ME312". JJM is still having problems with their WINOPS. JJM started working on new barge "ME308" (after 1130hrs) with base capping "sand blend". KC did not verify displacement of that barge prior to use of new materials. No new capping work occurred during the rest of the shift. Working platform relocated further downstream in Area B. Night Shift: 1:30PM to 9:30PM JJM resumed base capping drops in Area B at 1358hrs. The Contractor is still working on barge "ME308". Capping stopped, and work platform relocated (required anchor moves) at 1447hrs. JJM did not resume capping work until app. 1858hrs. At app. 2030hrs. the next JJM survey shift crew left for the platform. JJM's second shift capping crew does not start until 2200hrs. The Contractor continued base capping with only occasional short stops until 2130hrs.
Miscellaneous:	The hopper barge "Swan Island" has been offloaded and cleaned up at Terminal 25, but has not yet departed.
Safety/Accidents:	No incidents/accidents were reported to KC by the Contractor.
Problems Encountered & Resolutions:	JJM is still trying to work out sporadic problems with their WINOPS.
Test Conducted:	KCEL (Bob) on site at app. 1500hrs. to take Flood Tide tests for turbidity levels during the capping operation.
Work Rejected:	
Instructions Given to	

Ukwenga Oleru Project Représentative (Date)

Keith Nordlund, Construction Inspector (Date)



Initiated:		·
Visitors to Site	RobMatheison, JJM; Ukwenga Oleru, KC/CM	
Equipment Used	JJM Survey Boat "Doppler"	2 crew persons
	Tender Tug "Mary Margaret" Anchor Tender "Miller 102" Materials Barges, "ME312", "ME308"	1 supervisor
	Capping Barge/ Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216"	3 crew persons





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)


TIME WORK STARTED: TIME WORK STOPPED:

			Date			
Year	-	Moi	nth	Day	Ins	spector
2004		1		25	11	K/ KN
		D	ay of the	<u>Week</u>		
Sat	Sun	Moi	n Tue	Wed	Thu	Fri
	Х					
			Weathe	r		
				_		
Clear	1	PC	Overcas	t Fo	og	Rain
			х			
			Temperat	1150		
10-32	3,	2-55	55-70	. <u>ure</u> 70-	95	85+
10-34			33-70	70-	.02	037
		<u>X</u>				

Construction Activities:	Day Shift: 6:00AM to 2:00PM
	JJM continued the capping phase of this Contract at the site in Area B, working overnight on
,	barges "ME308" and "ME310". The "ME209/ME216" working platform for the capping
 -	operation, is continuing base capping work in Area B and the east end of Area A (former buffer
	zone). JJM continued capping through last night, and started up with new shift crew this
	morning at app. 0600hrs. Capping work continued with occasional short stops and barge
	relocations until app. 0855hrs., when Contractor changed shift crew. At app. 1015hrs,
1	completed emptying hopper barge "ME310". By app. 1140hrs, that barge had departed. A new
	flat barge "Hoquiam", arrived at the working platform and was readied by 1230hrs. JJM started
	working on new barge "Hoquiam" (after 1255hrs) with base capping "sand blend". KC did not
	verify displacement of that barge prior to use of new materials.
	Night Shift: 1:30PM to 9:30PM
	JJM continued base capping drops at E. end Area A. The Contractor is working on barge
	"Hoquiam". Capping stopped, and work platform relocated upstream to Area B at 1410hrs.
	Capping resumed at app. 1415hrs. and continued until 1430hrs. stop for lubing maintenance.
	At app. 1449hrs, base capping resumed. The Contractor continued base capping until app.
	5:00PM, when the platform relocated. JJM used the relocation/reorientation to begin a series of
·	other events. JJM reworked the anchors, re-surveyed Area B, and rearranged sand piles on the
	"Hoquiam". Capping did not resume before the end of this shift (2130hrs).
Miscellaneous:	Miller surveyors on site at 0835hrs. They have been working the site in conjunction with the
	base capping operation to verify placement meets the Contract's proposed grade for that
	material, as well as providing a cross-check to confirm that WINOPS is giving correct data.
ľ	JJM second shift survey crew arrived at 2100hrs.
·	Cameron McIntosh left for Tacoma, Wa. at app. 1520hrs
Safety/Accidents:	No incidents/accidents were reported to KC by the Contractor.
Problems Encountered &	JJM's Hitachi excavator would not reach sand piled on the West (starboard) side of the barge
Resolutions:	"Hoquiam". It required periodic reworking of the sand stockpiles to prevent the barge from
ixesolutions.	listing.
Test Conducted:	KCEL (Bob) on site at app. 1550hrs. to take Flood Tide turbidity tests during the capping
lest Conducted:	ROLL (DOD) on site at app. 1330ins. to take Flood Tide turbidity tests during the capping

Ukwenga Oleru Project Representative (Date)

Keith Nordland, Construction Inspector (Date)



	operation.	
Work Rejected:		
Instructions Given to Contractor & Changes Initiated:		····
Visitors to Site		
Equipment Used	JJM Survey Boat "Doppler"	2 crew persons
	Tender Tug "Mary Margaret"	2 crew persons
	Anchor Tender "Miller 102"	1 supervisor
	Materials Barges, "ME310", "Hoquiam"	
	Capping Barge/ Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew persons





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

				_	_	
Year		Mont	ın	Day	Ins	spector
2004	1			28	г	b/KN
		<u>Da</u>	y of the V	<u>eek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
				Х		
			Weather	•		
Clear	P	C	Overcast	Fo	g	Rain
			X			X
		<u>I</u>	emperatu	<u>re</u>		
10-32	32	-55	55-70	70-8	85	85+
	-	X				

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM On site this morning at app. 6AM. Crew is placing capping material (base sand). New barge arrived on site early morning. Crew placing base cap in the upstream end of Area of A. Night Shift: 1:30PM to 9:30PM JJM continued base material capping at the S. end of Area A. JJM is still working on the flatbed barge "Western Venture". JJM stopped at app. 1400hrs and attempted to relocate upstream in Area B (Note: JJM has had previous problems with shorter cables than they require to make some moves on the anchor winches). JJM resumed base capping after relocating back to the E. end of Area A interface with Area B at app. 1645hrs. JJM moved downstream in Area A. JJM continued with the base capping, taking only occasional short stops (for lubing, rearranging sand on the barge, relocations, etc.) until the end of this shift.
Miscellaneous:	Miller survey crew on site to monitor capping activities. JJM took delivery of a new cable spool during the shift.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC.

	Problems Encountered &	Tom Johnson (Miller) informed R. Brunke today (1200hrs) that they had overfilled base cap			
I	Resolutions:	material along app. 60' of the outside (channel side) berm of Area B. Also in the slopes in area			
١		B the base cap material is not holding on the slope and is piling up at bottom of slope in a			
1		natural repose close to 3H/1V not 2H/1V.			
l		They have talked to Bruce McDonald(Anchor Environmental) about these two issues.			
Į		According to Tom Johnson, Bruce directed them to build up the slope toe to allow the slope to			

Ukwenga Oleru Project Representative (Date)

Randall Brunke.

Keith Nordlund, Construction Inspector (Date)

	take the material and hold on the slope. The overfilled area will need to be removed down to design elevation. Contacted Ukwenga Oleru and informed him of the situation. Met later at the site office (1230-1330hrs) with Ukwenga, Tom Johnson, Len Miller, K. Nordlund, and Miller surveyor to further discuss the issue				
Test Conducted:	KC lab on site this morning after 0800hrs to take Flood Tide water turbidity test. KC lab on site at 1130hrs, to take Ebb Tide water turbidity test.				
Work Rejected:					
Instructions Given to					
Contractor & Changes					
Initiated:					
Visitors to Site	Ukwenga Oleru, KC/CM; Colin Waggoner, NO/	AA Consult.; Marla Steinhoff, NOAA			
Equipment Used	JJM survey boat "Doppler"	2 person crew			
	Tender Tug "Mary Margaret"	1 supervisor			
	(2)Anchor Tending Platforms				
	Capping Barge/Hitachi 1800 Excav. "ME209"				
	Capping Barge/Crane/Loader "ME216"	3 crew person			
	Flatbed Barge "Western Venture"				





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			<u>Date</u>			
Year				D		4
Year	-	Mont	in	Day	In:	spector
2004		1		29	r	b/KN
		<u>Da</u>	y of the V	/eek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
					X	
			Weather	•		
Clear	P	C	Overcast	Fo	g	Rain
		•	X			X
		<u>T</u>	Cemperatu	<u>re</u>		
10-32	32	-55	55-70	70-8	15	85+
		X				

Construction Activities:	Day Shift: 6:00AM to 2:00PM				
	On site this morning at 6:00AM. JJM completed emptying the flatbed barge "Western				
	Venture", and is now working from the flatbed barge "Hoquiam" ("Western Venture" departed				
	around 8AM). Crew is placing capping material (base cap) in Area A at app. station 6+00.				
	Miller changed shift crew at app.10:00AM. No new capping work by the Contractor after app.				
	9:30AM.				
	Crew pulled barge away from capping rig at Noon and relocated capping platform next to the				
	Port of Seattle pier at job site to rework anchor lines and perform other equipment				
	maintenance.				
1	Night Shift: 1:30PM to 9:30PM				
	JJM work platform ME209/ME216 is still tied up to the dock mooring dolphins installing new				
	anchor cables. JJM is currently taking base capping material from the flatbed barge				
	"Hoquiam". JJM surveyors continued working Area A. JJM had not resumed base capping by				
İ	the end of this shift				
İ					
1					
Miscellaneous:					
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.				
Problems Encountered &					
Resolutions:					
Test Conducted:	KCEL on site at 0845hrs. to take Flood Tide turbidity tests. KCEL cancelled the afternoon test				
1	because the JJM work platform was still moored throughout the test window. Spoke with				
	KCEL(Stephanie) about field test results from yesterday and today, and passed that information				
	on to JJM (Tom Johnson). The Contractor is not doing anything different from any previous				

Ukwenga Oleru Project/Representative (Date)

Randall Brunke,

Keith Nordlund, Construction Inspector (Date)



	capping shift work, but for whatever reason, the field turbidity results this morning were high. Note: There has been high rainfall totals throughout the area over the last 48hrs. Several rivers are on flood watch, and the urban SDs are dumping large volumes of runoff water into the Duwamish R. There have been problems with determining what the results of field turbidity tests actually indicate during previous heavy rainfall episodes.				
Work Rejected:					
Instructions Given to	·				
Contractor & Changes					
Initiated:					
Visitors to Site	Patty Miller, Kym Takasaki, USACE; Chuck Mil	ller, Tom Johnson, JJM			
Equipment Used	JJM survey boat "Doppler" 2 person crew				
1	Tender Tug "Mary Margaret"	1 supervisor (L. Miller)			
	(2)Anchor Tending Floats				
İ	Capping Barge/Hitachi 1800 Excav. "ME209"				
	Capping Barge/4000WCrane/Loader "ME216" 3 crew persons				
	Flatbed Barge "Hoquiam"				





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)

TIME WORK STARTED: TIME WORK STOPPED

[
Year		Mont	:h	Day	Ins	spector
2004		1		30		rb
		Da	y of the V	Veek		-
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						х
			Weather			
Clear	P	C	Overcast	Fog	<u> </u>	Rain
			Xwindy			
		<u>T</u>	emperatu	<u>ire</u>		
10-32	32-	-55	55-70	70-8	5	85+
		<				

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM On site this morning at exactly 6:00AM. Crew is in process of placing base cap material in Area A. Crew stopped capping at app 6:45AM Talked to Len Miller at 10:25AM. He informed me that the reason JJM is not capping this morning is that they are saving the rest of the capping material on the "Hoquiam" for Area B rework. JJM will rework areas that surveys show is not holding capping material at design slopes (agreement worked out with B. McDonald and KC). They are waiting for the best tide situation (need low tide to work the slopes with their equipment). JJM Capping rig moved upstream to Area B. Anchors need to be repositioned to order to access area B Night Shift: 1:30PM to 9:30PM
Miscellaneous:	JJM work platform "ME209/ME216" was still tied up to the dock mooring dolphins. JJM worked on the upstream anchors until app. 5:30PM. At 8:05PM crew for the next shift began arriving at the site. JJM working platform did not perform any capping work before the end of this shift.
9.64.14	
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered & Resolutions:	
Test Conducted:	KC lab on site this morning at app 8:00AM to take water turbidity test. However due to no capping activities no test was conducted.
Work Rejected:	
Instructions Given to	
Contractor & Changes	

Ukwenga Oleru Project Representative (Date)

Randall Brunke

Keith Nordlund, Construction Inspector (Date)



REPORT NUMBER:

CONTRACT NUMBER: #C33027C

Initiated:		
Visitors to Site		-
Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	•
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Hoquiam"	•





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)

TIME WORK STARTED: TIME WORK STOPPED

Yea	r	Mon	ıth	Day	Ins	pector
200	4	1		31		RO/KN
		<u>D</u> :	ay of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
x						
			Weather	<u>.</u>		
Clear	I	PC	Overcast	Fo	g	Rain
			X			X
			Temperati	ıre		
10-32	32	2-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM			
i	Arrived on site this morning at 7:00am. No capping activity was observed. Barge "Hoquiam"			
	appears empty. KC was informed by JJM (Dean, surveyor) that the barge was emptied of base			
	capping blend sand from app. 2:00am. until app. 5:00am.			
1	At app. 11:48pm., the "Hoquiam" departed the site. Flatbed barge "ITB-270" arrived at 1:00			
	pm. with new base cap material, and was moored to the east side of the work platform.			
1 .	Night Shift: 1:30PM to 9:30PM			
	JJM resumed base capping in Area A at app.1340hrs., between app. sta. 04+00 and 06+00. JJM			
	stopped base capping at app.1430hrs. and resumed again at app.1543hrs. JJM continued			
	capping with occasional short (10-15min. breaks) until a long capping stop at 1743hrs. JJM			
1	resumed again at app.1852hrs. JJM continued base capping in Area A, working N. toward app.			
1	sta. 02+00 until the end of this shift.			
1				
}				
Miscellaneous:	At app. 8:00am., JJM Day Shift Surveyors (John, Mike) arrived to relieve JJM Night Shift			
wiscenaneous.	Survey (Dean). Between 9:40am. & 10:00am., Night Shift Captain, Greg Anderson (306 772-			
	2548 cell.) relieved the Day Shift crew Captain, Stu (253 606-9992 cell), and Chris and John.			
	At 11:50pm., JJM Surveyors gave KC/CM a copy of latest survey data showing the locations of			
	base capping bucket drops (WinOPS), and updated (1/29/04) Survey Charts. JJM Night Shift			
	Survey crew arrived at 2000hrs. to relieve the JJM Day surveyors.			
:				
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.			
Problems Encountered &	Note: Per JJM(Greg, Dean) barge "ITB-270" did not arrive as expected at 1:30am. this			
Resolutions:	morning. Greg informed me that JJM did not remove the excess capping material in Area B			
	during last night's Ebb tide because of continued anchor problems. JJM will try again at			
	7:00pm. during Ebb tide. The Contractor also informed KC (Oleru) that barge "JTB-270",			
	bringing material from Canada, was stopped at US Customs. But that it had been released, and			

Ukwenga Oleru Project Representative (Date)



	that Miller had dispatched another Tug Boat to tow the barge to the site. The barge arrived at 1:00pm.				
Test Conducted:	KCEL did not take any turbidity tests this day.				
Work Rejected:					
Instructions Given to Contractor & Changes Initiated:					
Visitors to Site					
Equipment Used	JJM survey boat "Doppler" Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barges "Hoquiam", "ITB-270"	2 person crew 1 supervisor (Greg Anderson, nights: 1-306 772-2548 cell.; Stu, days: 1-253 606-9992 cell.) 3 crew person			





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			Dute			
Year	r	Month	,	Day	ln	spector
2004	1	2	•	1		K/KN
		_	of the W	/eek	•	OIC.
Sat	Sun	Mon	Tue	Wed	Thu	Fri
		1,1011	140	******	1 114	711
	Х		***			
			<u>Weather</u>			
Clear	ī	ec c	Overcast	Fog	n	Rain
	-		J TCI Cast	1.0	5	Naiii
		X				
1			mperatu	<u>re</u>		
10-32	32	-55	55-70	70-8	35	85+
]		X				

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM (I. Khilfeh)
	Arrived at site app. 5:50am. Contractor is still emptying flatbed barge "ITB-270" in Area A.
	Contractor continued sporadic base capping work until app. 7:40am. JJM the began a slow
	process of moving the working platform "ME209/ME216" upstream to area B. The Contractor
	completed the move to Area B by 11:40am. The work platform was still on standby by the end of this shift.
	Night Shift: 1:30PM to 9:30PM (K. Nordlund)
	Contractor began moving platform downstream toward Area A app. 1555hrs. At 1700hrs. JJM moved downstream again to the Area A interface with Area B (former buffer zone). JJM
	resumed base capping with the balance of blend sand in the "ITB-270". JJM continued working
	slowly upstream base capping as the platform moved. JJM stopped capping at 1800hrs. JJM
	resumed base capping at 1855hrs. (See Problems Encountered below for further details), and
	continued with only occasional stops until barge was emptied.
Miscellaneous:	A large part of the time required for the process of moving the barge required moving the
	(nearly empty) flatbed barge "ITB-270" from the E. (land) side of the working platform to the
	W. (channel) side of the platform with the "Mary Margaret".
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	At 1905hrs, received cellphone call from Len Miller informing me that an hydraulic cylinder
Resolutions:	had burned out on the Hitachi Excavator, that kept the jaws from completely closing. Len said
	that JJM would not be reworking spots in Area B (that JJM surveys show were high), but
	would spend the balance of Night Shift attempting as best they could to complete placing the
· .	rest of the blend sand in the barge.
Test Conducted:	KCEL did not take any turbidity tests this day.
Work Rejected:	
Instructions Given to	
Contractor & Changes	·
Initiated:	
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Iha Khilfeh, Construction Inspector (Date)



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
·	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "ITB-270"	· ·
		1





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

				<u> </u>	_	
Year	r	Mon	th	Day	ימו	spector
2004	\$	2		1	J)	K/KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
	X					
			Weather	[
Clear	P	C	Overcast	Fo	g	Rain
		X				
1		1	<u> Cemperati</u>	ıre		
10-32	32	-55	55-70	70-8	35	85+
		X	_			

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM (I. Khilfeh)
Construction Activities:	
	Arrived at site app. 5:50am. Contractor is still emptying flatbed barge "ITB-270" in Area A.
	Contractor continued sporadic base capping work until app. 7:40am. JJM the began a slow
	process of moving the working platform "ME209/ME216" upstream to area B. The Contractor
	completed the move to Area B by 11:40am. The work platform was still on standby by the end of this shift.
	Night Shift: 1:30PM to 9:30PM (K. Nordlund)
	Contractor began moving platform downstream toward Area A app. 1555hrs. At 1700hrs. JJM
	moved downstream again to the Area A interface with Area B (former buffer zone). JJM
	resumed base capping with the balance of blend sand in the "ITB-270". JJM continued working
	slowly upstream base capping as the platform moved. JJM stopped capping at 1800hrs. JJM
	resumed base capping at 1855hrs. (See Problems Encountered below for further details), and
	continued with only occasional stops until barge was emptied.
Miscellaneous:	A large part of the time required for the process of moving the barge required moving the
	(nearly empty) flatbed barge "ITB-270" from the E. (land) side of the working platform to the
	W. (channel) side of the platform with the "Mary Margaret".
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	At 1905hrs, received cellphone call from Len Miller informing me that an hydraulic cylinder
Resolutions:	had burned out on the Hitachi Excavator, that kept the jaws from completely closing. Len said
	that JJM would not be reworking spots in Area B (that JJM surveys show were high), but
	would spend the balance of Night Shift attempting as best they could to complete placing the
	rest of the blend sand in the barge.
Test Conducted:	KCEL did not take any turbidity tests this day.
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	·
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keitl Nordlund,

Iha Khilfeh, Construction Inspector (Date)



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
· ·	Flatbed Barge "ITB-270"	
		7





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

M	onth	Day	Ins	spector
	2	2		rb
	Day of the V	<u>Veek</u>		
Sun . Me	on Tue	Wed	Thu	Fri
У	ζ			
	Weather	_		
PC	Overcast	For	ס	Rain
		7	_	Х
		ıra		^
32-55			25	85+
X	23 70	,0-0		35.
	Sun . M	Day of the V Sun Mon Tue X Weather PC Overcast X Temperatu	2 2 Day of the Week Sun Mon Tue Wed X Weather PC Overcast For X Temperature	2 2 Day of the Week Sun Mon Tue Wed Thu X Weather PC Overcast Fog X Temperature

Date

Construction Activities:	ON site this morning at 6AM. Miller is not on site and no work activities noted
	·
	·
	·
<u> </u>	
Miscellaneous:	
Safety/Accidents:	
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	·
Initiated:	
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Iha Khilfeh, Construction Inspector (Date)



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "ITB-270"	
		1





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	Date			
				•
Mon	ith	Dav	Ins	pector
2		-		гb
_	av af tha V	_		10
Sun Mon	Tue	Wed	Thu	Fri
X				
	Weather			
PC	Overcast	For	,	Rain
• •		rog	•	Kain
	X			X
	Temperatu	re		
32-55	55-70	70-8	5	85+
Х				
	2 <u>D</u> Sun Mon X PC	Day of the V Sun Mon Tue X	Month Day 2 2 Day of the Week Sun Mon Tue Wed X Weather PC Overcast Fog X Temperature 32-55 55-70 70-8	Month Day Ins 2 2 Day of the Week Sun Mon Tue Wed Thu X Weather PC Overcast Fog X Temperature 32-55 55-70 70-85

Construction Activities:	ON site this morning at 6AM. Miller is not on site and no work activities noted
	and the work delivates noted
į į	
ļ	·
·	
	·
	·
7.4	
Miscellaneous:	
S. C. (1)	
Safety/Accidents:	
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Iha Khilfeh, Construction Inspector (Date)



Equipment Used	JJM survey boat "Doppler"	2 person crew
1	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "ITB-270"	





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Mon	th	Day	In	spector
2004]	2		3	I	b/KN
		<u>Da</u>	ay of the V	Veek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
			X			
			Weather	<u>r</u>		
Clear	F	C	Overcast	Fo	g	Rain
			· x		_	
			• •			
			<u>Cemperati</u>	_		
10-32	32	2-55	55-70	70-8	35	85+
	_	X				

Date

Construction Activities:	Day Shift: 6:00AM to 2:00PM (R. Brunke)
	On site this morning at 6:00AM. JJM is in process of changing out the bucket on the Hitachi
	1800 excavator. The hydraulic ram on the clamshell bucket is being rebuilt. Crew is installing a
	"rock skip" type bucket.
	New base capping material flatbed barge (Western Venture) was on site at 12:45PM, and is
	being moored to E. side of capping platform. Tug "Westrac" delivered the "Western Venture". Night Shift: 1:30PM to 9:30PM (K. Nordlund)
	JJM resumed base capping in Area A at app. 1409hrs., and stopped again at 1435hrs. JJM
	resumed capping at app. 1503hrs. and broke off capping at 1547hrs. JJM resumed capping at
	app. 1556hrs., and stopped at app. 1730hrs. to repair the Cat 966 Loader aboard the barge. JJM
	resumed base capping at 1800hrs. and continued with only occasional stops until the end of this shift.
Miscellaneous:	JJM stopped base capping at 1730hrs. Len Miller informed KC (Nordlund) that it was to make
	weld repairs to a pin that was going bad on the Cat 966 Loader aboard the barge. The loader is
	needed to fill the skip bucket currently being used by JJM.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	JJM had to change the bucket on the Hitachi 1800 Excavator. The hydraulic ram on the
Resolutions:	clamshell bucket is not working, and will require a rebuild. JJM is changing to a "rock skip" type bucket.
	Capping platform moved from Area B back to Area A during Day Shift. Miller did not want to
	cap in Area B with the new bucket. The new "rock skip" type bucket is unable to see depth
	without reconfiguring the DGPS/WinOps systems. KC (K. Nordlund) was informed by T.
	Johnson, JJM, at app. 1430hrs. that the clamshell bucket is expected back during Day Shift
	tomorrow, and at least part of that shift will be spent changing over the buckets on the Hitachi
	again.
Test Conducted:	KCEL was onsite at app. 1547hrs. to take Ebb Tide turbidity tests
Work Rejected:	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Randy Brunke, Construction Inspector (Date)



Instructions Given to Contractor & Changes Initiated:		
Visitors to Site	Tom Johnson, JJM; Ukwenga Oleru, KC/CM; C	olin Waggoner, NOAA Consult.
Equipment Used	JJM survey boat "Doppler" Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barge "Western Venture"	2 person crew 1 supervisor 3 crew person





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting (JJM)

TIME WORK STARTED: TIME WORK STOPPED

		Date			
Year	Mo	nth	Day	Inspecto	r
2004		2	4	rb/KN	
	<u> </u>	Day of the V	<u>Veek</u>		
Sat	Sun Mo	n Tue	Wed	Thu Fi	ri
			X		
		Weather	_		
Clear	PC	Overcast	Fog	Rain	1
		Х		X	
		Temperatu	ıre		
10-32	32-55	55-70		5 85+	
	X				

Miscellaneous: Miller surveyors on site this morning at app 8:00AM. Note: Spoke to Len Miller (on the dock, 1430hrs.) regarding the rebuild work on the clamshell bucket. He said that the shop rebuild is done, and delivery is still due today. He is trying to get a crew mechanics to reassemble the bucket on the barge, and minimize the downtime on the capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. JIM stopped base capping at app. 12:00 noon to repair a deck winch. JJM resumed capping at 1:05PM. JJM stopped base capping at app. 1515hrs. to work on another problem with the loader. The crew then made a major platform shift, which was coupled with moving the cable anchors, and then decided to reinstall the clamshell bucket (per R. Matheison, JJM). Base capping work did not resume through the balance of this (KC) shift period. KCEL on site this morning at 8:00AM. Lab did not take water turbidity tests due to no capping activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer Problems Encountered section for other details). Work Rejected:	Construction Activities:	Day Shift: 6:00AM to 2:00PM (R. Brunke) On site this morning at 6:00AM. JJM is in process of placing base cap material (Western Venture). Crew capping in the downstream (Area A). Crew stopped at 7:48AM. Crew resumed capping at app 9:15AMCrew stopped capping at app 9:45AM. Crew resumed capping at 11:13AM. Night Shift: 1:30PM to 9:30PM (K. Nordlund) JJM stopped base capping at 1346hrs, and resumed again at app. 1400hrs. JJM is still using the "rock skip" they were using yesterday. JJM is working upstream between app. sta. 01+00 and 03+00. JJM stopped capping at app. 1515hrs. Crew persons for the JJM Night Shift began arriving onsite at 1955hrs. JJM did not resume base capping before the end of this (KC) shift
1430hrs.) regarding the rebuild work on the clamshell bucket. He said that the shop rebuild is done, and delivery is still due today. He is trying to get a crew mechanics to reassemble the bucket on the barge, and minimize the downtime on the capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. JJM stopped base capping at app. 12:00 noon to repair a deck winch. JJM resumed capping at 1:05PM. JJM stopped base capping at app. 1515hrs. to work on another problem with the loader. The crew then made a major platform shift, which was coupled with moving the cable anchors, and then decided to reinstall the clamshell bucket (per R. Matheison, JJM). Base capping work did not resume through the balance of this (KC) shift period. Test Conducted: KCEL on site this morning at 8:00AM. Lab did not take water turbidity tests due to no capping activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer Problems Encountered section for other details).		period.
Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & JJM stopped base capping at app. 12:00 noon to repair a deck winch. JJM resumed capping at 1:05PM. JJM stopped base capping at app. 1515hrs. to work on another problem with the loader. The crew then made a major platform shift, which was coupled with moving the cable anchors, and then decided to reinstall the clamshell bucket (per R. Matheison, JJM). Base capping work did not resume through the balance of this (KC) shift period. Test Conducted: KCEL on site this morning at 8:00AM. Lab did not take water turbidity tests due to no capping activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer Problems Encountered section for other details).	Miscellaneous:	1430hrs.) regarding the rebuild work on the clamshell bucket. He said that the shop rebuild is done, and delivery is still due today. He is trying to get a crew mechanics to reassemble the
1:05PM. JJM stopped base capping at app. 1515hrs. to work on another problem with the loader. The crew then made a major platform shift, which was coupled with moving the cable anchors, and then decided to reinstall the clamshell bucket (per R. Matheison, JJM). Base capping work did not resume through the balance of this (KC) shift period. Test Conducted: KCEL on site this morning at 8:00AM. Lab did not take water turbidity tests due to no capping activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer Problems Encountered section for other details).	Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer Problems Encountered section for other details).		1:05PM. JJM stopped base capping at app. 1515hrs. to work on another problem with the loader. The crew then made a major platform shift, which was coupled with moving the cable anchors, and then decided to reinstall the clamshell bucket (per R. Matheison, JJM). Base
Work Rejected:	Test Conducted:	activity during the test window. KCEL did not take turbidity tests this afternoon because there was no capping work in progress during the afternoon testing window (loader repair; refer
	Work Rejected:	

1 2/6/04 Kwenga Oleru Project Representative (Date)

Keith Nordlund,

Randall Brunke, Construction Inspector (Date)



Instructions Given to Contractor & Changes Initiated:		
Visitors to Site	Rob Matheison, JJM	
Equipment Used	JJM survey boat "Doppler" Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barge "Western Venture"	2 person crew 1 supervisor (Len Miller) 3 crew person





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

İ						
Year	r	Mont	th	Day	Ins	spector
2004	ļ	2		5		b/KN
		<u>Da</u>	y of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
					X	
			Weather	:		
Clear	P	C	Overcast	Fo	g	Rain
		X				
1		<u>1</u>	'emperatu	<u>ıre</u>		
10-32	32	2-55	55-70	70-8	35	85+
		X				

<u>Date</u>

Construction Activities: Day Shift: 6:00AM to 2:00PM (R. Brunke) On site this morning at 6:00AM. No Capping activities by JJM noted at 6:00AM. JJM resumed capping at 7:03AM "Western Venture". Crew placed a couple of buckets of sand a then stopped at app. 7:15AM. JJM is moving arm of excavator around but not placing any material. Crew started again to place sand at 7:35AM. JJM stopped for shift change at app. 9:30AM. Crew resumed capping at app 10:30AM, and continued until the end of this shift. Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the "Hoquiam" at 1430hrs. JJM stopped at 1620hrs. to lube the bucket and relocate the platform			
resumed capping at 7:03AM "Western Venture". Crew placed a couple of buckets of sand a then stopped at app. 7:15AM. JJM is moving arm of excavator around but not placing any material. Crew started again to place sand at 7:35AM. JJM stopped for shift change at app. 9:30AM. Crew resumed capping at app 10:30AM, and continued until the end of this shift. Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the	_		
then stopped at app. 7:15AM. JJM is moving arm of excavator around but not placing any material. Crew started again to place sand at 7:35AM. JJM stopped for shift change at app. 9:30AM. Crew resumed capping at app 10:30AM, and continued until the end of this shift. Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the	_		
material. Crew started again to place sand at 7:35AM. JJM stopped for shift change at app. 9:30AM. Crew resumed capping at app 10:30AM, and continued until the end of this shift. Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the	ıd		
9:30AM. Crew resumed capping at app 10:30AM, and continued until the end of this shift. Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the			
Night Shift: 1:30PM to 9:30PM (K. Nordlund) The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the			
The barge "Hoquiam" arrived at the site at app. 1326hrs and was moored on the starboard (channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the			
(channel) side of the capping platform while the "Western Venture" was unloaded. "Western Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the			
Venture" departed the site under tow at app. 1427hrs. JJM began base capping from the			
"Hoquiam" at 1430hrs. JJM stopped at 1620hrs, to lube the bucket and relocate the platform			
JJM resumed base capping at app. 1715hrs. Capping stopped again at 1820hrs., and platform			
began relocating upstream to Area B. JJM moved N. of app. sta. 12+00 at 2015hrs., but did			
not resume base work before the end of this (KC) shift period due to further mechanical			
problems.			
Miscellaneous: JJM has repaired and replaced the hydraulics for the bucket on the Hitachi Excavator. JJM is			
using the clamshell bucket for base capping during this shift period.			
Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period.			
Problems Encountered & JJM stopped at 1620hrs. to lube the bucket and relocate the platform. During the shot move,			
Resolutions: JJM lost the WinOPS. JJM resumed base capping at 1714hrs.			
Test Conducted: .KCEL on site this morning to take water turbidity sample (8:40AM). Test was taken.			
KCEL on site this afternoon to take water turbidity sample (12:40PM). Test was taken.			
Work Rejected:			
Instructions Given to Meeting at site trailer: JJM, KC and Bruce McDonald, AE, met to discuss the capping			
Contractor & Changes progress based on the latest Survey results presented by the JJM Surveyors (2/3/04 issue).			
Initiated: Miller is concerned that some of the base material they have deposited is being scoured out of	г		
redeposited by the current. Bruce McDonald did his best to address the JJM capping issues,	nd		
give Miller a set of priorities to address based on the latest surveys. The Contractor is			
especially interested in finding an acceptable solution in Area B with the EofB and KC, as (p			


Molern

3/2/04

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Randall Brunke Construction Inspector (Date)



·	Randy Daggitt) Miller plans on sending the next flatbed barge from Canada with 5000+ tons of Quarry spalls.		
Visitors to Site	Bruce McDonald, AE; Randy Daggitt, Wes Yewel, JJM; Ukwenga Oleru, KC/CM		
Equipment Used	JJM Survey boat "Doppler" 2 person crew		
	Tender Tug "Mary Margaret"	1 supervisor (Len Miller)	
	(2)Anchor Tender Floats		
	Capping Barge/Hitachi 1800 Excav. "ME209"		
	Capping Barge/Crane/Loader "ME216" 3 crew person		
	Flatbed Barges "Western Venture", "Hoquiam"		
	Charter Tug "Westrac"		
		1	





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•						
Year	M	onth	I	Day	Ins	spector	
2004		2		6	r	rb/KN	
		Day of	the W	<u>eek</u>			
Sat	Sun M	lon 1	Tue	Wed	Thu	Fri	
						х	
		We	ather				
Clear	PC	Ove	rcast	Fo	g	Rain	
			X			х	
		Temp	eratur	·e			
10-32	32-55		5-70	 70-8	35	85+	
	Х						

Date

	report 6:00AM to 2:00PM (Randy Brunke)			
On site this	morning at 6:00AM. Crew is in process of placing base cap blend sand (barge			
Hoquiam)				
	ed at approx. 8:30AM after re-positioning capping platform and am crew change			
(approxima	tely 10:0AM). JJM resumed capping at 10:30AM.			
	Night Shift 1:30PM to 9:30PM (Nordlund)			
	JJM was placing base blend sand in Area A, between app. sta. 05+00 and 06+00, Rt. of Base			
	M Grid Plan), at the beginning of this shift. JJM is removing (blend sand) base cap			
	material from the flatbed barge "Hoquiam". JJM emptied the "Hoquiam" by app. 1510hrs. At			
	s the "Coldecker Straits" flatbed barge was tied up along the starboard (channel)			
	apping platform. This is JJM' first barge of quarry spalls. The work platform began			
1	oward Area B at app. 1800hrs. No new capping work occurred before the end of this			
shift.				
	JJM, informed KC (Brunke) that last night JJM corrected the high and low spots of			
	Area B (due to a past WinOPS malfunction) to meet the plans, and Engineer			
	d approved revisions. JJM Surveyors completed a re-survey of Area B this			
	nd the results were reviewed by B. McDonald, AE.			
	ctor did not report any accidents/incidents to KC this shift period.			
Problems Encountered &	·			
Resolutions:				
I :	unke: As of this date, no further water turbidity testing is required per phone			
	n with one Fritz G. (KCEL).			
Work Rejected:				
r i i	one conversation from Ukwenga Oleru, with instructions for the Contractor			
	urther work in Area B, as follows: JJM is approved to place quarry spalls between			
	and 08+70; between sta. 11+10 and project S.endline (followup with B. McDonald,			
	ontractor is directed to correct base cap low spots prior to placing quarry spalls as			
follows: sta	. 08+80, between 95'-110'; sta. 09+20, between 100'-110'; sta. 09+40, between			

URO 3/2/0

Ukwenga Oleru Project Representative (Date)

KeithOvordlund,

Ranndy Brunke, Construction Inspector (Date)



	85'-110'; sta. 09+80, between 95'-110'; sta. 10+20, between 95'-110'; sta. 11+00, between 95'-110' (All above sta. and offsets are per the JJM Site Grid Plan).		
Visitors to Site			
Equipment Used	JJM survey boat "Doppler"	2 person crew	
• •	Tender Tug "Mary Margaret"	1 supervisor	
	(2)Anchor Tender Floats		
	Capping Barge/Hitachi 1800 Excav. "ME209"		
	Capping Barge/Crane/Loader "ME216"	3 crew person	
	Flatbed Barges "Hoquiam", "Coldecker Straits"		
	SeaLink Charter Tug "Neva Straits"		
		1	





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		<u>Date</u>	_		
Year	- Mo	nth	Day	Ins	spector
2004		2	7		RO/KN
	Ī	Day of the V	Veek_		
Sat	Sun Mo	n Tue	Wed	Thu	Fri
x					
		Weather	<u>.</u>		
	n.a		_		. .
Clear	PC	Overcast	Fog	3	Rain
İ		X			
10-32	22.55	Temperatu			051
10-32	32-55 X	55-70	70-8	3	85+

previously approved areas (per B. McDonald, EofR) between sta. 07+00 and 08+70; between sta. 11+10 to sta. 13+80. Capping stopped. At 1215hrs, Quarry spalls barge was removed from site and moored across the river at Island Tug & Barge wharf to enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs, flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to	Construction Activities:	Day Shift report 6:00AM to 2:00PM (U. Oleru)	
start of this shift. At app. 0800hrs, Miller completed placing quarry spalls in previously approved areas (per B. McDonald, EofR) between sta. 07+00 and 08+70; between sta. 11+10 to sta. 13+80. Capping stopped. At 1215hrs, Quarry spalls barge was removed from site and moored across the river at Island Tug & Barge wharf to enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs, flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: Problems Encountered & At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to	1.		
previously approved areas (per B. McDonald, EofR) between sta. 07+00 and 08+70; between sta. 11+10 to sta. 13+80. Capping stopped. At 1215hrs, Quarry spalls barge was removed from site and moored across the river at Island Tug & Barge wharf to enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs, flatbed barge "TTB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 133hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to		start of this shift. At app. 0800hrs, Miller completed placing quarry spalls in	
was removed from site and moored across the river at Island Tug & Barge wharf to enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to		previously approved areas (per B. McDonald, EofR) between sta. 07+00 and 08+70;	
was removed from site and moored across the river at Island Tug & Barge wharf to enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to			
enable receipt of another base capping barge. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "TTB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that			
JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to ISTANCON (Nordlund) that			
was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to		Night Shift 1:30PM to 9:30PM (Nordlund)	
was getting ready to place additional base capping material in low spots indicated on their most recent survey data (re: F. Report 2/6/04 for other details). The additional work was directed by KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to		JJM was still awaiting the next barge of blend sand at the beginning of this shift. Contractor	
KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to		was getting ready to place additional base capping material in low spots indicated on their most	
the starboard (channel) side of the working platform. JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to the starboard app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1500hrs. Contractor moved back to Area A, and resumed capping work at app. 1500hrs. Contractor moved back to Area A, and resumed capping work at app. 1500hrs. Contractor moved back to Area A, and resumed capping work at app. 1510hrs. Contractor moved back to Area A, and resumed capping work at app. 1500hrs. Contractor moved back to Area A, and resumed capping work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchoring is specifically prohibited in the work area to accidents/incidents to KC this shift period.			
JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream. Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to Is15hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		KC and the EofR. By 1415hrs., flatbed barge "ITB-270" was towed up river, and tied up along	
Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app. 1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. KCEL turbidity testing has been cancelled. Instructions Given to			
1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to	İ	JJM resumed base capping at app. 1430hrs. at app. sta. 11+00. Work proceeded downstream.	
resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to Is15hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		Capping stopped at app. 1510hrs. to rework anchors. JJM resumed capping work at app.	
stops, until the end of this shift period. Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to Stopping work, and to confirm possible completion of additional work, and to confirm possible completion of additional work, and to confirm possible completion of additional work, and to confirm possible completion of additional work, and to confirm possible completion of additional work, and to confirm possible completion of additional work area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area, to anchor their work area,		1600hrs. Capping stopped again at app. 1700hrs. Contractor moved back to Area A, and	
Miscellaneous: JJM Surveyors on site to monitor the capping work, and to confirm possible completion of additional work on Area B base capping. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to Is 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that	1	resumed base capping at app. 1733hrs. JJM continued base capping, with only occasional	
additional work on Area B base capping. The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		stops, until the end of this shift period.	
Safety/Accidents: Problems Encountered & Resolutions: At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: Work Rejected: Instructions Given to The Contractor did not report any accidents/incidents to KC this shift period. At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. KCEL turbidity testing has been cancelled. Work Rejected: 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that	Miscellaneous:	JJM Surveyors on site to monitor the capping work, and to confirm possible completion of	
Problems Encountered & Resolutions: At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: Work Rejected: Instructions Given to At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area, to anchor their working platform.		additional work on Area B base capping.	
Resolutions: anchor their working platform. Per the Contract, spud anchoring is specifically prohibited in the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that	Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.	
the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that	Problems Encountered &	At KC's (Oleru) direction, Miller raised one spud that they had lowered, in the work area, to	
the course of the job in the Duwamish R. channel, but this is the first time they have been observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that	Resolutions:	anchor their working platform. Per the Contract, spud anchoring is specifically prohibited <u>in</u>	
observed doing it in the work site. Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		the work area during the capping work (re: Sect. 2221, 3.03B.). JJM has dropped spuds during	
Test Conducted: KCEL turbidity testing has been cancelled. Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		,	
Work Rejected: Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that			
Instructions Given to 1815hrs. conversation with R. Daggitt, JJM: JJM informed KC/CM (Nordlund) that		KCEL turbidity testing has been cancelled.	
Contractor & Changes Surveyors had completed resurvey of Area B. The Survey showed undated info on the rework			
Surveyors had completed result by or ruled B. The our by showed updated into. On the towork	Contractor & Changes	Surveyors had completed resurvey of Area B. The Survey showed updated info. on the rework	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund Construction Inspector (Date)



Initiated:	noted above in this Report. Randy Daggitt said that JJM would continue base capping tonight, and that the new info. was being sent via Internet to Bruce McDonald, the EofR. KC (Nordlund) informed Randy Daggitt that CM would be expecting to hear from Bruce (McDonald), and would inform JJM if, and/or when they were approved to proceed with further quarry spall capping in Area B. At app. 1940hrs. received phone call from Bruce McDonald saying that he had just reviewed th latest survey results, and JJM could proceed with further quarry spall capping in the areas approved. JJM (R. Daggitt) was given the "go ahead" at 1948hrs., after a phone call by K. Nordlund to Ukwenga Oleru, with the same information.					
Visitors to Site	Rob Matheison, JJM	Rob Matheison, JJM				
Equipment Used	JJM survey boat "Doppler"	2 person crew				
	Tender Tug "Mary Margaret"	1 supervisor				
	(2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barges "ITB-270", "Coldecker Straits" SeaLink Charter Tug "Neva Straits"	3 crew person				





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			Bute			
•						
Year	r	Mon	th	Day	In:	spector
2004	1	2		8		K/KN
		Da	y of the V	Veek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
	X					
			Weather	<u>.</u>		
Clear	I	PC	Overcast	Fo	g	Rain
			Х			X
]	<u> Temperati</u>	<u>ıre</u>		
10-32	32	2-55	55-70	70-8	35	85+
		X				


Date

Construction Activities:	Day Shift report 6:00AM to 2:00PM (Iha Khilfeh) On site this morning at 6:00AM. JJM is placing base cap blend sand (barge ITB-270) Crew stopped at approx. 8:30AM after re-positioning capping platform and barge. JJM changed work crews(approximately 10:0AM). JJM continued activities on the work platform, but no new capping progress. JJM did not resume capping until app. 11:50AM, and continued with only occasional short stops until the end of shift. Night Shift 1:30PM to 9:30PM (Nordlund) JJM was placing base blend sand in Area A, between app. sta. 02+00 and 03+00, Left of Base Line at app. offset -60 (per JJM Grid Plan), at the beginning of this shift. JJM is removing base
	cap material from the flatbed barge "ITB-270". JJM emptied the "ITB-270" by app. 1330hrs. JJM removed their 966D loader from the barge at 1343hrs. At app. 1350hrs the tug "Westpoint" left with the "ITB-270", and a second tug "Westrac", brought the The "Straits Cold Decker" flatbed barge (quarry spalls) back over from Island Tug&Barge berth. The "Straits Cold Decker" flatbed barge was tied up along the starboard (channel) side of the capping platform. The work platform began moving S. toward Area B at app.1430hrs. JJM finally reached Area B, and resumed quarry spall capping by app. 1740hrs. (re: Problems Encountered for other details). JJM continued capping work with only occasional short stops until the end of this (KC) shift period.
Miscellaneous:	JJM Surveyors were on to monitor work in Areas and B this afternoon.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Note: at 1530hrs. KC (K. Nordlund) was informed by JJM (R. Daggitt) that another cable
Resolutions:	anchor winch had broken on the Working Platform.
Test Conducted:	As of this 2/6/04, no further water turbidity testing is required by KCEL, per phone
	conversation with one Fritz G. (KCEL) and CM (R. Brunke).
Work Rejected:	
Instructions Given to	
Contractor & Changes	

Ukwenga Oleru Project Representative (Date)

Tha Khilfeh,

Keith Nordlund, , Construction Inspectors (Date)



Initiated:					
Visitors to Site	R. Matheison, Randy Daggitt (weekend designated mgmt.), Bob Rudd, JJM				
Equipment Used	JJM survey boat "Doppler"	2 person crew			
	Tender Tug "Mary Margaret"	1 supervisor			
	(2)Anchor Tender Floats				
	Capping Barge/Hitachi 1800 Excav. "ME209"				
	Capping Barge/Crane/Loader "ME216"	3 crew person			
	Barges "Hoquiam", "Straits Cold Decker"				
	Charter Tugs "Westpoint", "Westrac"				
		7			





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			Date			
İ						
Year	Г	Month		Day	Ins	spector
2004	!	2		9	r	b/KN
		Day	of the V	/eek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
		X				
		3	Weather			
Clear	PC)vercast	Fog	5	Rain
	pm.			am.		
	•		mperatu	гe		
10-32	32-5		55-70	70-8	5	85+
.5-52	X	_	55 70	,0-0		057
Ī	Λ					

Construction Activities:	Day Shift report 6:00AM to 2:00PM (Randy Brunke)
	On site this morning at 6:00AM. Crew is in process of placing base capping (blend sand)
(material from the flatbed barge "Western Venture". The flatbed barge "Straits Cold Decker"
	(quarry spalls) is tied up again at Island T&B dock. Base cap material is being placed in Area B
	app. 11+00 on 1st slope and bench from shore. Capping stopped At 9:45AM for crew shift
	change. Capping resumed a 10:20AM.
	Crew moved anchors at app. 12:00PM to app. 1:40PM. Crew is now setup in front of the 144
	inch outfall and siphon area at station 5+90 next to shore.
1	Day Shift report 1:30PM to 9:30PM (K. Nordlund)
	At app. 1345hrs., an hydraulic hose ruptured on the upper arm of the Hitachi 1800 Excavator.
	Base capping resumed at app. 1710hrs., immediately SW. of the 144" SD. JJM stopped
	capping at app 1800hrs. and relocated upstream to the SE corner of Area A. JJM resumed base
	capping at 1824hrs. Base capping stopped again at 1842hrs. for relocation activities, JJM
ĺ	resumed capping at app. 1915hrs. JJM stopped at 2035hrs. to relocate anchors and do routine
	maintenance. JJM continued capping with relocations from E. to W. along the S. end of Area
	A.
Miscellaneous:	JJM Surveyors on site to monitor the base capping work, and to confirm extent of completion
	of new work on Area B quarry spall capping.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	At app. 1345hrs., an hydraulic hose ruptured on the upper arm of the Hitachi 1800 Excavator.
Resolutions:	Because of the location of the break, and the extent of spilled oil, JJM was forced to send out
	for a taller ladder than was on the work platform. JJM also had to route out an apparent
	problem with their GPS (the repeater is located on top of the excavator arm) that occurred
	when the hydraulic line broke. Base capping resumed at app. 1710hrs.
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	

URO

3/2/04

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



Visitors to Site	Randy Daggitt, Rob Matheison, JJM			
Equipment Used	JJM survey boat "Doppler"	2 person crew		
	Tender Tug "Mary Margaret"	1 supervisor (Len Miller)		
<u> </u>	(2)Anchor Tender Floats	1		
	Capping Barge/Hitachi 1800 Excav. "ME209"			
	Capping Barge/Crane/Loader "ME216"	3 crew person		
	Flatbed Barge "Western Venture"			
]		





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Mo	onth	Dav	Ins	pector
	2	10		b/KN
]	Day of the V	Veek		
Sun Mo	n Tue	Wed	Thu	Fri
	Х			
	Weather	r		
		•		
PC	Overcast	Fo	g	Rain
				,s
	Temperati	ire	•	
32-55			35	85+
	22 . 0	, 3 c	-	
	<u>]</u> Sun Mo	Sun Mon Tue X Weather PC Overcast Temperate 32-55 55-70	2 10	2 10 r

Date

Construction Activities:	Day shift (6AM to 1:20DM) Dandy I Daysto
Construction Activities:	Day shift (6AM to 1:30PM) Randy L Brunke
	Crew is not capping this morning. They are on self-imposed standby awaiting King County
	review of latest survey results taken by Miller on 2-9-04 and this morning. Survey results were
	sent via e-mail to Bruce McDonald (Anchor Environmental) KC Consultant. The survey is for
	Area B and the upstream of area A.
ì	The Barge "Western Venture" is currently moored to Capping platform with app 20% of base
	cap material left on board. JJM (re: Len Miller) wants to save remaining base cap material in
İ	case more material is required after KC reviews the latest survey results.
	Night Shift: 1:30PM to 9:30AM (K. Nordlund)
	The Contractor was still on standby at the beginning of this shift. Made cell-phone call to
	Ukwenga Oleru at 1445hrs. and copied down the latest information received from B.
	McDonald review of survey data sent to him from JJM. That information was passed on to JJM
	(Len Miller). JJM resumed base capping in Area A between app. sta. 06+00 and 07+00 after
	,
	1754hrs. JJM continued working downstream, with occasional short stops until the end of the
	shift.
Miscellaneous:	JJM Surveyors on site to monitor the base capping work.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	Made cell-phone call to Ukwenga Oleru at 1445hrs. and copied down the latest JJM survey
Contractor & Changes	review information received by KC from B. McDonald (AE consult.) in the form of an E/M.
Initiated:	Bruce informed KC that he was at home sick, but that he had reviewed information sent to his
	PC this day from JJM as doc. Master Profile 0210-0700-1180.DWG. KC (Nordlund) phoned
	JJM (Len Miller) oout on the Work platform with a list of acceptable areas, and areas requiring
	further work to meet the Contract docs. (per B. McDonald). Len maintained that two docs. had
	been sent to B. McDonald within the last 24 hours by JJM, and that (he felt) some of the
<u> </u>	been sent to 2. Mezonara whim the last 2 moute by sitti, and that the low) some of the

URO 3/Z/O4 Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



	information that KC was relaying to him did not reflect additional work performed on slopes Area A (sta. 07+00 to 8+40; offset -200 to -185) that JJM had sent to B. McDonald this morning. Note: JJM later confirmed (Rudd, Miller) that the CD that had the additional information had not been sent to the Engineer, as they had originally thought.			
Visitors to Site	Ukwenga Oleru, KC			
Equipment Used	JJM survey boat "Doppler"	2 person crew		
-	Tender Tug "Mary Margaret"	l supervisor (Len Miller)		
	(2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209"			
	Capping Barge/Crane/Loader "ME216"	3 crew person		
	Flatbed Barge "Western Venture"			





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			•			
Year	•	Moi	nth	Day	In	spector
2004		2	!	11		b/KN
		<u>D</u>	ay of the	<u>Week</u>		
Sat	Sun	Mo	n Tue	Wed	Thu	Fri
				X		
			Weathe	r		
				_		
Clear	P	C	Overcas	t Fo	g	Rain
х					_	
			<u>Temperat</u>	nre		
10-32	32	-55	55-70	<u>ure</u> 70-8	85	85+
		m.	pm.	70-0		
			Рии.			

Date

Construction Activities:	Device (00 A Mar. 1 20 DM (D. 1 1 D. 1)
Construction Activities:	Day shift: 6:00AM to 1:30PM (Randy L Brunke)
	On site this morning at 6:00AM. Crew is in-process of placing quarry spalls from the flatbed
	barge "Straits Cold Decker". Crew placing spalls in Area A and B from approximately station
	7+00 to 13+80. JJM continued with only occasional short stops until the end of this shift.
	Night Shift: 1:30PM to 9:30AM (K. Nordlund)
	At the beginning of this shift, JJM Work platform was moving upstream, spreading quarry
	spalls from the "Straits Cold Decker" in Area B. JJM is correcting borderline "light" spots, as
	determined by the Engineer's (re: B. McDonald, AE) review of the latest JJM survey data
	from Arong A and B. III atomical successions and a succession of the latest JJM survey data
	from Areas A and B. JJM stopped quarry spall capping at app. 1510hrs. JJM resumed capping
	at 1545hrs. JJM repositioned anchors at app. 1600hrs, ad did not resume capping until after
	1800hrs. Contractor continued, with occasional stops, until the "Straits Cold Decker" was
	emptied at app.2100hrs. The next barge was not on site by the end of this (KC) shift period.
Miscellaneous:	JJM Surveyors on site to monitor the base capping work.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	Note: at app. 1745hrs. spoke by cell-phone with Ukwenga Oleru regarding a request by Len
Contractor & Changes	Miller to use habitat mix in a manner that had been discussed directly between Len and Bruce
Initiated:	McDonald earlier that day. Ukwenga said that the area discussed with Len Miller to use the
	"habitat mix" was acceptable to Bruce, who had discussed the matter earlier with KC. Bruce
	sent an E/M to KC (Oleru) regarding the items discussed with (re: attached E/M).
Visitors to Site	Allison US/EPA on site at app 1PM today
Visitors to Site	Amson Corder A on site at app Trivi today

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



REPORT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Straits Cold Decker"	





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	<u>Date</u>					
Year	M	onth	Day	Ins	pector	
2004		2	12		b/KN	
		Day of the \	Veek	-		
Sat	Sun Mo	on Tue	Wed	Thu	Fri	
				X		
		Weathe	<u>r</u>			
Clear	PC	Overcas	t Fo	g	Rain	
х						
		Temperat	<u>ure</u>			
10-32	32-55	55-70	70-8	35	85+	
	am	pm				

Construction Activities: Day shift: 6:00AM to 1:30PM (Randy L Brunke) On site this morning at 6AM. Currently crew is not placing material. Crew placing base capping material at app. 6:45AM. Material is blend sand from the "Western Provider". JJM is working in Area A, between approximately station 5+00 to 6+00. Contractor continued base capping with only occasional short stops until the end of this shift. Night Shift: 1:30PM to 9:30AM (K. Nordlund) Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor did not report any accidents/incidents to KC this shift period. JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (ten Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M). John Miller, Scott Jacob, JJM; Uk	Companyation Antiquities	D 1:54. (.00 + 164. + 20 DM (D. 1 + D. 1 -)	
capping material at app. 6:45AM. Material is blend sand from the "Western Provider". JJM is working in Area A, between approximately station 5+00 to 6+00. Contractor continued base capping with only occasional short stops until the end of this shift. Night Shift: 1:30PM to 9:30AM (K. Nordhund) Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Construction Activities:		
working in Area A, between approximately station 5+00 to 6+00. Contractor continued base capping with only occasional short stops until the end of this shift. Night Shift: 1:30PM to 9:30AM (K. Nordlund) Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
capping with only occasional short stops until the end of this shift. Night Shift: 1:30PM to 9:30AM (K. Nordlund) Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app.1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
Night Shift: 1:30PM to 9:30AM (K. Nordlund) Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
Contractor is continuing base capping operations in Area A. They are working from the "Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
"Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half , "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).		Night Shift: 1:30PM to 9:30AM (K. Nordlund)	
"Western Provider", which has base cap blend sand, and arrived on the site last evening. JJM continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half , "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).		Contractor is continuing base capping operations in Area A. They are working from the	
continued base capping, with only occasional short stops, until the "Western Provider" was emptied at app.1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half , "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	·		
emptied at app. 1800hrs. The 966D Loader was picked from the barge, and the barge was towed ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
ETD 1840hrs. JJM began offloading the flatbed barge "ITB-270" in Area A at app. 1930hrs. JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
JJM continued base capping with only occasional short stops until the end of this shift. Note: It was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	1		
was (per Bob Rudd, JJM) JJM's intention to attempt placing the "habitat mix" near the shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
shoreline within the exist. rip-rap boundaries. That work did not happen until after the end of this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	ì		
this KC shift period. Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
Miscellaneous: JJM Surveyors on site to monitor the base capping work. The flatbed barge "ITB-270" was tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	į		
tied up at Island Tug &Barge during the day. It is split-loaded with half the load base cap blend sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Missellanses		
sand, and the other half, "habitat mix". It was towed by a Charter Tug over for unloading by JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Miscenaneous:		
JJM, ETA 1850hrs. Safety/Accidents: The Contractor did not report any accidents/incidents to KC this shift period. Problems Encountered & Resolutions: Test Conducted: . Work Rejected: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).			
Safety/Accidents: Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: Initiated: The Contractor did not report any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period. Interport any accidents/incidents to KC this shift period.			
Problems Encountered & Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: Unitiated: U			
Resolutions: Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.	
Test Conducted: Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Problems Encountered &		
Work Rejected: Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Resolutions:		
Instructions Given to Contractor & Changes Initiated: JJM requested a modification to the placement sequencing in the Contract, as regards the base blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Test Conducted:	•	
Contractor & Changes Initiated: blend sand, habitat mix, and rip rap in Areas A and B. The Engineer has discussed the matter with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Work Rejected:		
Initiated: with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with JJM (re: attached E/M).	Instructions Given to	JJM requested a modification to the placement sequencing in the Contract, as regards the base	
JJM (re: attached E/M).	Contractor & Changes		
——————————————————————————————————————	Initiated:	with JJM (Len Miller), and has issued a E/M to KC regarding the primary items discussed with	
Visitors to Site John Miller, Scott Jacob, JJM; Ukwenga Oleru, KC	}	JJM (re: attached E/M).	
	Visitors to Site	John Miller, Scott Jacob, JJM; Ukwenga Oleru, KC	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



Equipment Used	JJM survey boat "Doppler"	2 person crew
\	Tender Tug "Mary Margaret"	1 supervisor
}	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
İ	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barges "ITB-270", "Western Provider"	-
		1





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•					
				٠.		
Year	Г	Mont	th	Day	In	spector
2004	ţ	2		13		b/KN
		Da	y of the V	Veek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						х
			Weather			^
			vveather	•		
Clear	10	PC	Overcast	E.	_	Rain
Clear		C	Overcast	Fo	5	Kam
X						
		1	emperati	ire		
10-32	32	-55	55-70	70-8	15	85+
	a	m.	pm.			

Date

Construction Activities:	1st Shift, 6AM to 2PM; Randy Brunke
1	On site this morning at 6AM. Crew is in-process of placing material (Area A)
	off the "ITB -270". At 8:30AM crew moved capping platform up to existing rock bulkhead
	(shore) area just downstream of the finger pier to place habitat mix over existing rock
	bulkhead, area A (high tide is at 9:16AM). Crew is placing habitat mix in this area, working
	downstream along existing rock bulkhead. Stopped at 9:15AM. There was a JJM shift change
	at 10AM. Capping resumed same area at 10:40AM.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	By the start of this shift, JJM had moved out from shoreline in Area A, and were not placing any capping materials. By app. 1400hrs, JJM had moved the work platform upstream, and
	began re-grading high quarry spall spots into marginally low areas in the SE. comer of Area A
	and in Area B(re: Problems Encountered section below for further details). JJM alternated
	this re-grading work with the spreading of "habitat mix" in those zones of Areas A and B
	where quarry spall work had been approved. Work proceeded in this manner, with the
1 .	contractor taking occasional stops to relocate, re-survey, and/or perform routine maintenance
	until the end of this shift.
Miscellaneous:	JJM Surveyors on site to monitor the capping work, and to verify the re-grading of quarry
	spalls in Areas A and B.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	JJM began regrading high spots into marginally low areas in the SE. corner of Area A after
Resolutions:	1400hrs. (tide was on the Ebb). Other low spots in Area B were given a similar treatment. The
	rework was part of a plan worked out between the Engineer (B. McDonald, AE) and L. Miller,
}	JJM. KC (Oleru) received the new information via E/Mail, and passed it on to KC site staff as
į	a printout copy. JJM voluntarily agreed with the Engineer (to do the rework) to resolve any
	marginally questionable quarry spall areas just prior to spreading habitat mix from the "ITB -
1	270" in those areas. R. Brunke contacted B. McDonald to corroborate and clarify information
1	received by cell-phone from L. Miller (re: E/Mail 2/13/04, 8:39AM McDonald to Oleru, for
	further details).
Test Conducted:	·

URO 3/2/04

Ukwenga Oleru Project/Representative (Date)

Keith Nordlund,



Work Rejected:		
Instructions Given to		
Contractor & Changes		
Initiated:		
Visitors to Site		
Equipment Used	JJM survey boat "Doppler" Tender Tug "Mary Margaret" (2)Anchor Tender Floats	2 person crew 1 supervisor
	Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barge "ITB-270"	3 crew person





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		•				
•,				_	_	_
Year	r	Mon	th	Day	In.	spector
2004	Į.	2		14	I	K/KN
		<u>D</u> :	ay of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
х						
			Weather	r		
				_		
Clear	F	° C	Overcast	Fo	g	Rain
	X					showers
			<u>Temperati</u>	<u>ıre</u>		
. 10-32	32	-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:	ISI CLICA CARMAN OPEN, UNIVERSITY
Construction Activities:	1" Shift, 6AM to 2PM; Iha Khilfeh
İ	On site this morning at app. 6:00AM. Crew is in the process of removing base capping material
	(Area A) off the "Western Venture" (The "ITB-270" was completed during the night). At app.
<u> </u>	6:35AM, JJM moved work platform upstream. No materials were offloaded before the platform
	moved downstream again at app. 9:00AM, JJM finally resumed base capping at app 9:15AM,
	and stopped again at 9:45AM (just before shift change). JJM changed shift crews at app.
	10:00AM. JJM is placing base capping material, and then stopping occasionally to allow the
	966D Loader a chance to move materials on the flatbed barge. JJM resumed capping at app.
	10:35AM. JJM stopped capping again at 11:30AM. JJM began relocating the Work platform at
	that time, and reached new downstream location at app. 12:40PM. Capping resumed at
İ	12:50PM. JJM stopped base capping again at 1:10PM
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	By the start of this shift, JJM had resumed placing base capping materials in Area A, between
	app. sta. 03+00 and 04+00. JJM stopped base capping at app. 1445hrs, and moved the work
	platform upstream. JJM resumed capping at app. 1500hrs. JJM stopped again at 1830hrs. at
	app. sta. 06+00. JJM resumed capping at 1840hrs. JJM continued base capping with occasional
	stops to redistribute barge sand, relocate, and/or perform routine maintenance until the end of
	this shift.
Miscellaneous:	JJM Surveyors on site to monitor the capping work. JJM Night shift Survey crew began
	arriving at the site at 2000hrs.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	JJM management were in Tacoma, Wa., until 1830hrs.Bob Rudd stopped into the site office at
Resolutions:	that time. He informed K. Nordlund that JJM was trying to organize a meeting that day with B.
	McDonald to readjust the base capping quantities, and have him review JJM's latest survey
1	data (that has not yet been seen by the KC Proj. Rep.) to get approval from him for unloading a
	barge full of rip-rap that was due in during the (President's Day Holiday) weekend. K.
	Nordlund informed Mr. Rudd that agreements reached in that manner were not binding on KC.
Test Conducted:	
Work Rejected:	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Iha Khilfeh, Construction Inspector (Date)



Instructions Given to Contractor & Changes Initiated:		
Visitors to Site		
Equipment Used	JJM survey boat "Doppler" Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216" Flatbed Barge "Western Venture"	2 person crew 1 supervisor 3 crew person





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	r	Mont	h	Day	Ir	spector
2004	l	2		15		IK/KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
	х					
			Weather	•		
			,	-		
Clear	P	C	Overcast	Fog	g	Rain
	X					showers
		<u>T</u>	emperatu	<u>ire</u>		
10-32	32	-55	55-70	70-8	35	85+
		X				

Construction Activities:	1st Shift, 6AM to 2PM; Iha Khilfeh
	On site this morning at app. 6:00AM. No materials were offloaded from the flatbed barge
	"Western Service", before the platform moved upstream again at app. 1:00PM. Prior to that
	time, the only work on the barge consisted of the 966D Loader moving base cap blend sand
	materials on the flatbed barge so they could be more easily offloaded by the 1800 Excavator.
	JJM is placing base capping material in Area A between app. sta. 03+00 and 04+00.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	At the start of this shift, JJM was placing base capping materials in Area A, between app. sta.
	03+00 and 04+00. JJM stopped base capping at app. 1625hrs, and allowed the Loader to
	rearrange stockpile. At 1710hrs., the platform cut the barge loose, the Westrac II charter tug
	took charge of the "Western Service", and moved that barge over to Island Tug & Barge on
	standby. JJM retrieved the "Western Service", and tied up to the work platform at app.
	2000hrs. JJM continued moving material on the barge with the Loader, but did not resume
	capping again until after 2053hrs. JJM continued base capping through the end of this
	(KC)shift period.
Miscellaneous:	JJM Surveyors on site to monitor and survey the capping work. A good part of the morning
	shift was spent with JJM Surveyors re-surveying Area A. JJM changed one shift crew at
	app.10:00AM. Note: was informed by L. Miller, JJM, that the next barge that JJM expected
	was loaded with rip-rap. The tow company has determined that that barge is overloaded, and
	has refused the haul from Canada until part of the load is removed. JJM Night shift Survey
	crew began arriving at the site at 2000hrs.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	JJM management personnel were not on site for most of the 1st Shift. There was one short visit
Resolutions:	by John Miller this morning. KC (K. Nordlund) cell-phoned JJM (Len Miller) at app. 1335hrs.
	to find out why there had been virtually no capping for almost the entire (KC) 1st Shift, and
	because KC inspector, I. Khilfeh, had not received any information from the on site crew. Len
	said he didn't know, but would contact the Work platform and find out for KC. At app.
	1500hrs. Len called back and said that, there was no major mechanical problems, but that the
	barge was standing by for Survey update, and that is why no new capping work occurred.

(RO 3/2/04

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,

Iha Khilfeh, Construction Inspector (Date)



	JJM resumed work at app. 1705hrs, with blend sand stored on a platform named "Miller 308", KC (Nordlund) phoned Bob Rudd to ask what material was on that small barge, and was it intended for this jobsite. During the course of the phone call, John Miller and Randy Daggitt walked into the site office, KC ended the phone call with Mr. Rudd, and asked the same question to Msrs. Miller and Daggitt, KC was informed that the "Miller 308" was part of a job for Foss, and that none of that material would be used at this site, KC (Nordlund) also informed Mr. Daggitt that there were problems today establishing a "line of communications" with JJM site management. Mr. Daggitt said that George Tucker was in charge today, KC (Nordlund) said that no one had informed KC of that person's designation until this conversation.			
Test Conducted:				
Work Rejected:	·	_		
Instructions Given to				
Contractor & Changes				
Initiated:				
Visitors to Site	John Miller, Randy Daggitt, JJM			
Equipment Used	JJM survey boat "Doppler"	2 person crew		
	Tender Tug "Mary Margaret"	1 supervisor		
1	(2)Anchor Tender Floats			
	Capping Barge/Hitachi 1800 Excav. "ME209"			
[Capping Barge/Crane/Loader "ME216"	3 crew person		
	Charter Tug "Westrac II"			
	Flatbed Barge "Western Service"			
]		





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	· Mo	onth	Day	Ins	spector	
2004	· :	2	16		rb	
	Ţ	Day of the V	<u>Veek</u>			
Sat	Sun Mo	n Tue	Wed	Thu	Fri	
	X					
		<u>Weather</u>	2			
Clear	PC	Overcast	Fog	g	Rain	
		X.	-			
		<u>Temperatu</u>	ıre			
10-32	32-55	55-70	70-8	35	85+	
	X					!

Construction Activities:	On site this morning at 6AM Crew currently is not placing any capping material. At 6:30AM crew moved a appeared to be a empty barge away from capping platform. No capping activities today due to no material/barge available.
Miscellaneous:	
Safety/Accidents:	
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	i .
Initiated:	
Visitors to Site	

URO 3/2/04
Ukwenga Olery Project Pennadan

Keith Nordlund.



JJM survey boat "Doppler"	2 person crew
Tender Tug "Mary Margaret"	1 supervisor
(2)Anchor Tender Floats	
Capping Barge/Hitachi 1800 Excav. "ME209"	
Capping Barge/Crane/Loader "ME216"	3 crew person
Flatbed Barge "ITB-270"	·
	<u> </u>
	Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216"





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Date						
Yea	r	Mo	nth	Day	In	spector
200	-			•	III:	
200	4	2		17		rb
		D	ay of the V	<u>Veek</u>		
Sat	Sun	Mo	n Tue	Wed	Thu	Fri
			x			
			Weather	•		
				_		
Clear		PC	Overcast	Fo	ġ.	Rain
				,	•	
			Х			
			Temperati	<u>ire</u>		
10-32		32-55	55-70	70-8	35	85+
		Х				

Construction Activities:	Day shift 6AM to 2PM
	On site this morning at 6AM. Currently there is no capping or work activities. Miller is on standby for a barge delivery. Miller received a barge (Hoquaim) of Rip Rap today at 12:45 PM. Crew moved
·	Capping platform to area B to start placing Rip Rap. Crew started placing material today at 1:52PM
X SCAZZZZZZZZZZZZZZZZ ZZV	
Safety/Accidents:	
Problems Encountered & Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to Contractor & Changes Initiated:	
Visitors to Site	



REPORT NUMBER:

CONTRACT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
·	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "ITB-270"	
		1





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	r	Mor	ıth	Day	In:	spector
2004		2		18	r	b/KN
		<u>D</u>	ay of the V	<u>Veek</u>		
Sat	Sun	Mor	Tue	Wed	Thu	Fri
				X		
• .	Weather					
Clear	P	'C	Overcast	Fo	g	Rain
	pm.		am		am	
			Temperati	ıre		
10-32	32	-55	55-70	70-8	85	85+
		X				i


Date

Construction Activities:	1" Shift, 6AM to 2PM; Randy Brunke
Constituction Activities.	
	On site this morning at 6:00AM. Crew is in-process of placing Rip-Rap from the flatbed barge
	"Hoquiam". This barge started unloading yesterday at 1:52PM. Crew stopped capping at
	8:40AM.
	Crew moved Capping platform to approximately station 14+00 and started placing rip-rap at
	11:54AM. Rip -rap was placed in this area yesterday but Survey results from Miller indicated
	there was not enough coverage (min 2' thickness) so they are placing additional material.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	JJM was completing the offloading of rip-rap in Area B at the beginning of this shift. The
	"Hoquiam" was substantially emptied at app.1540hrs. JJM took occasional bites of material
•	while they moved downstream to Area A, and waited for another barge associated with a
	contract they had at Foss. That barge arrived at app. 1840hrs. No new capping work occurred
	for this KC Contract until after the end of this shift.
Missellaneaur	
Miscellaneous:	JJM Surveyors on site to monitor and survey the capping work. (8:50AM) Surveyors mapping
	out Area B where rip-rap material placed on Night shift.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Note: At app. 1900hrs., JJM brought up (by Charter tug "Lucy Franco") an empty flatbed barge
Resolutions:	(the "Sunny Point", Ketchikan, AK.) intended for another contract JJM was doing for Foss. No
	new capping work occurred for this KC Contract until after the end of this (KC) shift period.
Test Conducted:	
Work Rejected:	·
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	Kym Takasaki, USACE

URO 3/2/04
Ukwenga Olem Project Represent

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	_
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Hoquiam"	
		-[





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		Date			
-					
Year	Month	1	Day	lns	pector
2004	2		19	_	/KN
	Day of the Week				
Sat	Sun Mon	Tue	Wed	Thu	Fri
				Х	
		Weather			
Clear	PC (Overcast	Fog	;	Rain
1		Х			
	Te	mperatu	re		
10-3	32-55	55-70		5	85+
/	X				

Construction Activities:	1 st Shift, 6AM to 2PM; Randy Brunke
	On site this morning at 6AM. Crew is in-process of placing base cap material in Area A at
	approx. station 6+00 offset -100 just upstream of siphons.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	At the start of this shift, JJM was offloading blend sand base capping material from the flatbed
	barge "Western Service" immediately W. of the 144" City of Seattle SD (app. sta. 06+00). JJM
	stopped capping at app. 1700hrs. to allow JJM Surveyors to re-survey Area A around the 144"
	SD and KC siphon. By the time JJM stopped capping at 1700hrs., the work platform had
	moved downstream to between app. sta. 02+00 and 03+00. Base capping resumed at app.
	1720hrs. Base capping stopped at app. 1750hrs. for survey work, for the 966D Loader to
	reposition materials, and to reposition a working anchor (re: B. Rudd, JJM). JJM did not
	resume base capping until app. 2050hrs. JJM completed the barge after the end of this (KC)
	shift period (B. Rudd, JJM, estimated there was app. 20% of the blend sand left on the barge).
Miscellaneous:	JJM Surveyors on site to monitor and survey the capping work. JJM stopped capping at app.
	1700hrs. to allow JJM Surveyors to re-survey Area A around the 144" SD and KC siphon
	between sta. 07+00 and 05+00. Survey work continued to follow the working platform
	downstream.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	Bruce McDonald, AE

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor (Len Miller)
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Western Service"	





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

						•
Year		Month	I	Day	In	spector
2004		2		20		b/KN
1		<u>Day</u>	of the W	<u>eek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						Х
		,	Weather			
Clear	PC	C	Overcast	Fog	3	Rain
	Х				٠.	
		Te	mperatu	re		
10-32	32-		55-70	— 70-8	5	85+
	X					

Date

Construction Activities:	1 st Shift, 6AM to 2PM; Randy Brunke
	On site this morning at 6:00AM. There were no capping activities by JJM. There was no new
	capping this (KC)Day Shift, because the Contractor did not have a new barge with capping
	material on site. JJM's next barge is scheduled to be on site is this coming Saturday, February
	the 21st, ETA 10:00AM.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	At the start of this (KC) Night Shift, JJM working platform was still on stand by at the
]	downstream end of the project site. The JJM working Platform had not begun moving upstream
	(taking advantage of a -0.9 Ebb Tide to rework areas where previous capping activities had
	occurred, and that had been determined by the Engineer and (KC) to be unacceptable by the
	Contract, after review of JJM's own latest Survey data) by the end of this (KC) shift period.
· ·	The Contractor had notified the Proj. Rep. earlier in the day that they would move upstream
	after app. 1900hrs. to start that rework.
Miscellaneous:	Miller surveyors are mapping out previous JJM capping in Area A (noted at 6:00AM).
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	KC (Oleru, Brunke, Nordlund) received word from the Engineer (B. McDonald, AE) this
Resolutions:	morning that concerned parties at the USF&WS, as well as the EPA had been apprised of all
	changes that had been made between KC, JJM and the Engineer to date regarding the capping.
ľ	Those concerned parties have not taken any exceptions to the KC approved capping changes to
	date. The concerned State and Federal agencies have agreed in principle to a single contract
	extension of up to two weeks for JJM, if necessary, with conditions. The Proj. Rep. has thus
·	far, forwarded an E/Mail message from B. McDonald, confirming that information to Project
	staff. The Proj. Rep. has also, forwarded that information by telephone to JJM (re: R. Daggitt,
	JJM).
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	

UKwenga Oleru Project Representative (Date)

Keith Nordlund,



Initiated:		
Visitors to Site		
Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	•
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
		•





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED


1						
						,
		- ·		_		
Year	r	Mont	h	Day	Ins	pector
2004	ļ	2		21	11	K/KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
X						
			Weather			
Clear	P	C (Overcast	Fog	g	Rain
	>	<				
		<u>T</u>	emperatu	<u>ire</u>		
10-32	32	-55	55-70	70-8	35	85+
	aı	n.	pm.			

Date

Construction Activities:	1 st Shift, 6AM to 2PM; lha Khilfeh			
Constituction Activities.	On site this morning at 6:00AM. JJM did not start moving the work platform upstream until			
i				
	app. 11:30AM. There were no new capping activities by JJM until app. 11:45AM. The			
	Contractor took advantage of the Ebb Tide to rework a few high spots remaining from previous			
	capping activities in Area B (as determined by the Engineer's evaluation of JJM's recent			
	Survey data). JJM also reworked the "habitat mix" on the flatbed barge "Western Venture",			
	with their 966D Loader. That barge was towed on site this morning, ETA 10:00AM.			
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund			
	At the start of this (KC) Night Shift, JJM working platform was reworking the high spots in			
	Area B noted above. JJM removed their Loader from the "Western Venture" at app. 1315hrs.			
	The "drop nose" barge "Sunny Point" was towed over to the work platform from a slip at			
	Island Tug & Barge by the Charter Tug "Island Chief" at app. 1320hrs. That barge was towed			
	in on the landward side of the working platform, and immediately loaded with "habitat mix"			
	from the "Western Venture". At ETD 1350hrs., the "Sunny Point" left the work platform for			
	the 144" SD outfall area. JJM began "habitat mix" placement at app. 1359hrs. with the 966D			
	Loader. JJM completed offloading work in the 144"SD Outfall area at app. 1542hrs. The tug &			
	barge returned to the platform, and the 966D Loader was offloaded prior to the tug leaving			
	with the "Sunny Point". JJM resumed reworking high spots in Area B, at app. 1620hrs. JJM			
	resumed new capping work (after app. 1850hrs.) with "habitat mix" in Area B, over previously			
	placed quarry spalls (re: sheets C5,C6 plans). Capping work continued with only occasional			
NACN-	short stops, through the end of this (KC) shift period.			
Miscellaneous:	Miller surveyors were on site to chart JJM capping activities in Areas A and B.			
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.			
Problems Encountered &	JJM had determined earlier in the Project that their work platform and equipment, as			
Resolutions:	configured, could not reach the bayed area N. of the 144" SD outfall to place "habitat mix" as			
	shown in the plans. JJM resolved the problem by towing the "drop nose" barge "Sunny Point"			
	to this site, and nosing it into those areas near the SD outfall at Flood Tide to place the app. 50			
	cu. yds. of "habitat" blend.			
	2			

Ukwenga Oleru Project Representative (D

Kerth Nordlund,



Test Conducted:		
Work Rejected:		
Instructions Given to		
Contractor & Changes		•
Initiated:		
Visitors to Site	John Miller, Rob Matheison, JJM	
Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	Charter Tug "Island Chief"	·
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excavator	3 crew persons
	"ME209"	
	Capping Barge/Crane/Loader "ME216"	
	Flatbed Barge "Western Venture"	
	Drop-nose Barge "Sunny Point"	
		·





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			Date			
Yea	r	Mo	nth	Day	In	spector
200	4	2	!	22	ľ	K/KN
	Day of the Week					
Sat	Sun	Mo	n Tue	Wed	Thu	Fri
	X					
			Weathe	<u>r</u>		
Clear	l	PC	Overcasi	t Fo	g	Rain
		Х				
			Temperat	ure		
10-32	32	2-55	55-70	70-	85	85+
	a	m.	pm.			

Construction Activities:	1st Shift, 6AM to 2PM; Iha Khilfeh
	On site this morning at 6:00AM. JJM was basically setting up the work platform until app. 8:35AM. The Contractor is still offloading materials from the "Western Venture". JJM capping with "habitat mix" over previously placed rip-rap in Area B until app. 9:35AM. JJM stopped at app. that time to change shift crews. JJM resumed "habitat mix" capping at app. 10:00AM, and continued with only occasional short stops until the end of this (KC) shift
	period.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
Miscellaneous:	At the start of this (KC) Shift, JJM working platform was capping with "habitat mix" in Area B, from the "Western Venture" as noted above. JJM continued proceeding downstream with new capping work with the "habitat mix" in Area B, over previously placed rip-rap (re: sheets C5,C6 plans). JJM stopped capping just before 1800hrs. to allow the Loader to move most of the remaining material on the barge over to the Excavator. JJM resumed capping at 1830hrs. JJM stopped again at 1900hrs. to allow the Loader to move materials over to the Excavator. Capping resumed at app.1931hrs., and continued with only occasional stops, until the "Western Venture" was emptied.
	Miller surveyors were on site to chart JJM capping activities in Area B.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered & Resolutions:	Note: was informed by B. Rudd, JJM that the next materials barge was due in the Seattle area after 2300hrs.
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	John Miller, JJM

Randy Brunke, Construction Inspector (Date)
The Khillel



Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excavator	
	"ME209"	3 crew persons
	Capping Barge/Crane/Loader "ME216"	
	Flatbed Barge "Western Venture"	





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

			Date		٠	
Yea	r	Mont	ih	Day	Ins	pector
2004	1	2		23		b/KN
		_	y of the V	-		· · · · · ·
Sat	Sun	Mon	Tue	Wed	Thu	Fri
		х				
			Weather			
				-		
Clear	P	' C	Overcast	Fo	g	Rain
			х			Light
						rains
		<u>T</u>	<u>emperatu</u>	re		
10-32	32	-55	55-70	70-8	35	85+
		X				

Construction Activities:	1st Shift, 6AM to 2PM; Randy Brunke
	On site this morning at 6AM. Crew is in-process of placing capping material. JJM is placing
	Rip-rap in Area A app. sta. 07+00, offset -50.
	Capping stopped at approx. 9:30AM for a shift change. JJM did not resume capping through
	the balance of this (KC) shift period.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	The Contractor was not placing capping material at the beginning of this (KC) shift period. The Contractor (L. Miller, JJM) notified KC (U. Oleru) that they were down to perform
	maintenance on their equipment, and to review the latest JJM survey data. The Contractor spent
	the balance of their Night Shift rearranging the load on one of their hopper barges moored out
	in the outer harbor.
1	
Miscellaneous:	Miller surveyors were on site to chart JJM capping activities in Area A.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Note: the flatbed barge "Hoquiam" was held up at U.S. Customs, and was not towed on site
Resolutions:	until this morning. Len Miller informed KC (Nordlund) at app. 1620hrs., that JJM was still
1	awaiting some sort of final documentation from US Customs prior to placement of any more
	materials from the "Hoquiam". It is the primary reason that nothing more was placed by JJM
	after 0930hrs. At app. 1630hrs., KC (Nordlund)received word from Len Miller, JJM, that
	problems with US Customs had not been resolved, and JJM would not be doing any capping
	using that barge until tomorrow morning.
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
	2/1/4///

Ukwenga Oleru Project Representative (Date



REPORT NUMBER: C33027C

Visitors to Site		
Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Hoquiam"	'





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>				
Year	Mo	nth	Day _.	Inspector
2004	2	•		rb/KN
	Ī	ay of the V	Veek_	
Sat	Sun Mo	n Tue	Wed	Thu Fri
		X		
		Weather		
		-		
Clear	PC	Overcast	Fog	Rain
		X		showers
	<u>Temperature</u>			
10-32	32-55	55-70	70-85	5 85+
	X			

Construction Activities:	1st Shift, 6AM to 2PM; Randy Brunke
	On site this morning at 6:00AM. No capping activities this morning and the Contractor is not
	on site. Crew arrived on site at 10:00AM. Crew is waiting word form the US Customs that
	the paperwork is completed on the "Hoquiam", and Miller is allowed to resume offloading rip-
	rap off that barge.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	The Contractor was still on "stand by" in Area A, at the beginning of this KC shift period.
	JJM's work started in the E. end of Area A. JJM received clearance from us Customs, and they
, al	resumed new capping work with rip-rap placement, and some reworking of previously capped
Special	locations, after app. 1500hrs. JJM stopped capping at app. 1745hrs. JJM resumed rework
	activity and rip-rap capping at app. 1830hrs., and stopped again at 1840hrs. for their Loader to
	catch up with the Excavator. JJM resumed new work at 1922hrs. JJM stopped capping work at
	app. 1940hrs. to repair a hydraulic leak. Capping work resumed after app. 2022hrs.
Miscellaneous:	It appeared that the spuds on the Capping derrick were down this morning. KC (R. Brunke)
]	talked to Len (Miller) about spuds and he told me that they are not all the way down. Miller
	Surveyors were on site to chart JJM capping activities in Area A.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Note: KC(U. Oleru) has requested a letter from JJM regarding the recent extensive "down
Resolutions:	time" regarding the capping work. This KC Contract is based in performance. KC (K.
	Nordlund) explained to B. Rudd, JJM, that KC considers that the timing of these JJM problems
	(right after the granting of a two-week conditional Contract extension) may be a coincidence,
	but they just look bad. Note2: JJM stopped capping work at app. 1940hrs. to repair an
	hydraulic leak. Per L. Miller, it was JJM's intent to continue to place both the regular and
	special graded rip-rap between app. sta. 07+00 and 08+50 in Area A through the balance of the
	night, once the leak repair was completed. Capping work resumed after app. 2022hrs.
Test Conducted:	·
Work Rejected:	
Instructions Given to	
Contractor & Changes	

Keith Nordlund,



Initiated:		
Visitors to Site		
Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 Supervisor (L. Miller; left site@2000hrs.)
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Hoquiam"	-
		1





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	- 1	Month	Day	,	Insi	pector
2004		2 25 rb/K				
	Day of the Week					
Sat	Sun !	Mon T	ue We	eđ	Thu	Fri
	· X					
		We	ather			
CI	200	•		_		
Clear	PC	Ovei	rcast	Fog		Rain
		. 3	(sl	nowers
<u>Temperature</u>						
10-32	32-5	5 55	-70	70-85	3	85+
	X					

C	I SECTION CARE ADDRESS I D. I. D. I.		
Construction Activities:	1" Shift, 6AM to 2PM; Randy Brunke		
	On site this morning at 6AM Crew is on site but currently no capping activities noted. At		
	7:35AM crew moved capping derrick close to shore at approx. station 8+00 to 9+00 offset-125.		
	Crew started placing rip-rap at 8:25AM. Capping stopped at 9:20AM. JJM capping and rework		
	activities in progress at 12:45PM.		
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund		
	JJM had stopped capping and rework activity in Area A, between app. sta. 05+00and 07+00, at		
	app. 1300hrs. JJM resumed rip-rap capping at app. 1400hrs. JJM stopped new capping work		
İ	from app. 1500hrs. to 1600hrs (re: Instructions Given-section below for other details). JJM		
	resumed reworking the grades, and new rip-rap capping shortly after 1600hrs. JJM continued		
	with only occasional short stops until the "Hoquiam" was emptied at app. 1735hrs. The		
	Contractor spent the balance of this (KC) shift period reworking high and low spots in their		
	previous materials placements as determined earlier this day by the Engineer's review of JJM		
	survey data. The barge "Western Venture" was not due to the sight until after 2200hrs.		
Miscellaneous:	Miller surveyors out on the water at 9:32AM to map out recent cap areas.		
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.		
Problems Encountered &			
Resolutions:			
Test Conducted:			
Work Rejected:			
Instructions Given to	JJM stopped new capping work from app. 1500hrs. to 1600hrs. to allow the Engineer to field		
Contractor & Changes	verify (from aboard the "Doppler", during an Ebb Tide) the condition of JJM's work along the		
Initiated:	site shoreline. The Engineer also reviewed new JJM survey data on board the Capping		
	platform and noted for additional work by the Contractor, areas that did not meet plans, specs		
	or approved revisions to the Contract.		
Visitors to Site	C. Waggoner, NOAA Consult.; B. McDonald, AE; Randy Daggitt, JJM		

Ukwenga Oleru, Project Representative (Date)

Keith Nordlund,



REPORT NUMBER: CONTRACT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
• •	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Hoquiam"	
		1





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		<u>Date</u>			
Year	Moi	nth	Day	Ins	spector
2004	2		26		rb
	Day of the Week				
Sat	Sun Moi	n Tue	Wed	Thu	Fri
				X	
		Weather			
Clear	PC	Overcast	Fog	}	Rain
		Х			Х
		Temperatu	<u>ire</u>		
10-32	32-55	55-70		5	85+
	X				

Construction Activities:	1" Shift, 6AM to 2PM; Randy Brunke
	On site this morning at 6:00AM. Crew on site. Currently JJM is not capping. The barge "Western Venture" arrived on site at app. 10:30PM last night with "habitat mix". Len (Miller) informed me at 7:10AM that they are having problems with their WinOPs GPS system and that is why they are not capping JJM began placing habitat mix from the "Western Venture" in Area A 12:44PM.
	2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	JJM was placing "habitat mix" from the "Western Venture", in Area A, at the beginning of this (KC) Shift period. Capping stopped at app. 1500hrs. to relocate work platform. JJM resumed
	capping and rework activities at app. 1515hrs. JJM stopped capping at 1740hrs. JJM resumed capping at app. 1750hrs. Capping work continued through the end of this (KC) shift period.
Miscellaneous:	Miller Surveyors (6:50AM) mapped out areas of previously capped high spots that were reworked last night. Survey crew also charted JJM capping activities in Area A.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Len Miller left the site today for awhile to purchase back-up hydraulic hose lengths for recently
Resolutions:	ruptured hydraulic hoses on the Hitachi 1800 Excavator.
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund



REPORT NUMBER: CONTRACT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
·	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Western Venture"	
		·





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Mor	nth	Day	In	spector
2004	1	2		27		b/KN
	Day of the Week					
Sat	Sun	Moi	n Tue	Wed	Thu	Fri
						X
			Weathe	<u>r</u>		
Clear	F	C	Overcas	t Fo	g	Rain
			X			X
			Temperat	<u>ure</u>		
10-32	32	2-55	55-70	70-	85	85+
		X				

Date

at mix off
ocations.
rea A to spots in a k in Area in moving al short
ked on
from the
ed prior
•
1 1 1

URO 3/2/04

Ukwenga Oleru Project Representative (Date)

Keith Nordlund,



REPORT NUMBER: CONTRACT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
1	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Flatbed Barge "Western Venture"	





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	r į	Month		Day	In	spector
2004	l	2		28	U	IO/KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
X						:
		2	Weather			
			-			
Clear	PC	C	vercast	Fo	g	Rain
х			X		•	
		Te	mperatu	re		
10-32	32-5	55	55-70	70-8	35	85+
	X					

Construction Activities:	1st Shift, 6AM to 2PM; U. Oleru
	On site this morning at 7:00AM. Crew on site. Crew is currently placing "habitat mix" off the
1	barge "Miller 310", in Area A just north of the outfall. JJM then stopped capping at about
İ	08:50AM to adjust anchor and survey the capped area. JJM changed crews at about 09:40AM.
	JJM moved barge and platform to N. of Area A, and dropped spuds (outside of the work site). 2nd Shift, 1:30PM to 9:30PM; K. Nordlund
	At the start of the shift, the Contractor was still anchored on their spuds N. of the project site.
	Per Ukwenga Oleru, JJM had not been doing any new capping since app. 12:00PM. Per
	information received from Len Miller at app. 1330hrs., JJM was going about the process of
	demobilizing the "M216" from this job site, since that work platform and it's equipment was
	no longer necessary to complete the Contract work. The "M216" left the platform under tow
	from the "Mary Margaret" at app. 1405hrs. JJM began reworking high spots along the channel
	edge of Area B between 1600hrs. and 1900hrs. Contractor spent the balance of this (KC) shift
1	period reworking the channel edge of Area A, while moving downstream. JJM also placed
	"habitat mix" along the shoreline in the NE quadrant of Area A.
Miscellaneous:	JJM Survey crew charted the most recent JJM capping and rework activities in Area A. Note:
	per L. Miller, their Night shift was the last shift working this weekend. Based on that
	information, paged the scheduled Sunday 1st Shift inspector, and cancelled the shift (per
	previous agreement with U. Oleru, Proj. Rep.).
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	
Resolutions:	
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	

Ukwenga Oleru Project Representative (Date)

Keith Nordlund, Construction Inspector (Date)



REPORT NUMBER: C33027C

Equipment Used	JJM survey boat "Doppler"	2 person crew
	Tender Tug "Mary Margaret"	1 supervisor
	(2)Anchor Tender Floats	
	Capping Barge/Hitachi 1800 Excav. "ME209"	
	Capping Barge/Crane/Loader "ME216"	3 crew person
	Barge "Miller 310"	
		1





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED


Yea	r	Mont	h	Day	In	spector
200	4	2		29		KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
	Х					
			Weather			
Clear	F	PC	Overcast	Fo	g	Rain
		x				
		<u>T</u>	emperati	ire		
10-32	32	2-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:	Sunday Shift, 1:00PM to 9:00PM; K. Nordlund At the start of the shift, the Contractor was moving up into Area A. JJM used the "Mary Margaret" to swing the "Miller 310" barge around for better access to the last of the "habitat mix" on board at app. 1400hrs. JJM began placing "habitat mix" in low spots in Area A after app. 1530hrs. JJM reworked high spots along the channel edge of Area A after app. 1620hrs. Contractor spent the balance of this (KC) shift period reworking the channel edge of Area A and B, and used up the balance of materials on the "Miller 310" as they worked upstream. Capping and rework ended at app.1900hrs. The JJM Survey crew continued their portion of the work.
Miscellaneous:	JJM Survey crew charted the most recent JJM capping and rework activities in Area A.
Safety/Accidents:	The Contractor did not report any accidents/incidents to KC this shift period.
Problems Encountered &	Note: Per phone call from Len Miller to KC (Nordlund, at home)this morning, JJM had not
Resolutions:	finished capping and rework last night, as they had originally thought. Len explained that everyone on the crew was "just getting too tired to go on." Per L. Miller last night, their 2/28/04 Night shift was the last shift working this weekend. Based on that information, the scheduled Sunday 1st Shift inspector was cancelled. K. Nordlund came in to cover the work after contacting U. Oleru, Proj. Rep.
Test Conducted:	
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	Ukwenga Oleru, KC Proj. Rep.

UR 0 3/2/04
Ukwenga Oleru Project Representative (Date)

Keith Nordlund, Construction Inspector (Date)



REPORT NUMBER: CONTRACT NUMBER: C33027C

JJM survey boat "Doppler"	2 person crew
Tender Tug "Mary Margaret"	l supervisor (Len Miller)
(2)Anchor Tender Floats	
Capping Barge/Hitachi 1800 Excav. "ME209"	
Capping Barge/Crane/Loader "ME216"	3 crew person
Barge "Miller 310"	
	1
	Tender Tug "Mary Margaret" (2)Anchor Tender Floats Capping Barge/Hitachi 1800 Excav. "ME209" Capping Barge/Crane/Loader "ME216"





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•					
Yea	r	Mor	oth	Day	I n:	spector
2003	3 .	11		17		rb
		<u>D</u>	ay of the V	<u>Week</u>		
Sat	Sun	Mor	1 Tue	Wed	Thu	Fri
		Х				
		••	Weathe	r		
			77.021110	_		
Clear	1	PC	Overcast	t Fo	g	Rain
10-32	3	2-55	Temperat 55-70	<u>ure</u> 70-8	35	85+

<u>Date</u>

Construction Activities:	Miller Contracting					
	Crew work Saturday the 15 th dredging terminal 25. See attached reports for	g. Crew dredged to shifts and sent a total of 2 barges to				
·	terrimar 25. See unacirca reports for					
	1 st Shift					
	Dredging resume today. Crew started Terminal 25 this morning around 7Al	I shift at 2AM and delivered a full barge(Swan Island) to M.				
		barge (Sand Island) and delivered full barge to Terminal				
	25 at Approx 12:45 PM					
	2 nd shift					
	Crew started dredging/ filling Barge approx 5PM.	(Swan Island) and delivered full barge to Terminal 25 at				
	Crew started dredging/ filling barge (Sand Island) and delivered full barge to Terminal 25 at approx 10:30PM					
	See Attached Miller reports					
	Dredge- Crystal Gayle	1- Supervisor				
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M Barges Sand Island/ Swan Island	2-Tug crew 2- Survey Crew				
	Survey Boat	2- burrey clew				
	Crew Boat					
Miscellaneous:						
	<u> </u>	2				

Ukwenga Oleru Project Representative (Date)



REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Safety/Accidents:					
Problems Encountered &					
Resolutions:				 · · · · · · · · · · · · · · · · · · ·	
Test Conducted:				 	
Work Rejected:				 	
Instructions Given to		•			
Contractor & Changes					
Initiated:					
Visitors to Site				 	
Equipment Used	1				
	1		·		





REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

		<u>Date</u>			
Year	Moi	nth	Day	Ins	spector
2003	11		18		rb
2005		ay of the V			
Sat S	Sun Moi	•	Wed	Thu	Fri
-		X			
		Weather			
		WEATHER	-		
Clear	PC	Overcast	Fo	ρ.	Rain
				9	
		m .			X
		Temperatu			A
10-32	32-55	55-70	70-1	85	85+
	X		•		

Construction Activities:	offloaded. Rabanco is not unloading	ay. The barges are sitting at Terminal 25 waiting to be barges at this time because according to Rabanco they nt of tonage for the time frame as stated in there contract.
	Dredge- Crystal Gayle	1- Supervisor
	Tug- Norton Bay	3- Dredge Crew
	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2- Survey Crew
	Survey Boat	
	Crew Boat	
Miscellaneous:		
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:		
Work Rejected:		
Instructions Given to		
Contractor & Changes		
Initiated:		
Visitors to Site		

URO 12/15/03

Ukwenga Oleru Project Representative (Date)

MMCM

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	November 18, 2003		Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First / Second			Х		-		

<u>Weather</u>	Clear	Х	Overcast		Fog	Х	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	X	Moderate		High			
Humidity	Dry		Medium	X	Humid	_		

Name of Visitors:	Company	Purpose of Visit	
			

Work Description Summary	Labour	Equipment	Materials
Dredging canceled due to inability to	Miller		
deliver sediment to off load site.	Supervision:	Survey Boat	Nil
Rebanco has limited delivery to	Randy Daggitt	Crew Boat	
2000 cubic yards per day.	Len Miller	i	
	Wes Yewell	STAND BY:	
No. 6 calculation of the control of	Rob Matheson	Dredge – Crystal	
No further dredging scheduled until		Gayle	
Nov. 20, 2:00am		Tug - Norton Bay	Î
	<u>McAmis</u>	Tug – Loren M	
Construction hydrographic survey	Supervision:	Barge - Sand Island	
continues.	Craig Chartrand	Barge - Swan Island	
Continues.			1
	Survey		
	John Hasall	Ì	ļ
	Mike Doratti		
	Geoff Methuen		·
	·		
			,
•		Ī	
		·	
		1	
			1

Initials of Miller representative __

A.m





D	E P	OR	ar Ì	Vri	м	DE	D.	
ĸ	ĽР	UK		71	W	Br.	ж:	

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•				
Year	r Mo	nth	Day	Ins	pector
2003	3 11		19		rb
	1	Day of the '	<u>Week</u>		
Sat	Sun Mo	n Tue	Wed	Tbu	Fri
			Х		
		Weathe	<u>:r</u>		
Clear	PC	Overcas	t Fo	g	Rain
		X			X
		Temperat	<u>ure</u>		
10-32	32-55	55-70	70-	85	85+
	X				

<u>Date</u>

Construction Activities:		y today. Barges are at Terminal 25 being offloaded today. land should be offload today and be available to Miller for
	Dredge- Crystal Gayle	1- Supervisor
	Tug- Norton Bay	3- Dredge Crew
	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2- Survey Crew
	Survey Boat Crew Boat	
Miscellaneous:	CICW DOAL	· · · · · · · · · · · · · · · · · · ·
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:		
Work Rejected:		
Instructions Given to		
Contractor & Changes Initiated:		
Visitors to Site		
Equipment Used	1	
=darkment open	_	
	<u> </u>	

Ukwenga Oleru Project Representative (Date)

QC 3A - DAILY OPERATIONS INFORMATION **DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT**

Date Work Performed:	November 19, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First / Second				Х			

Weather	Clear	Χ	Overcast		Fog	X	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	Х	Moderate		High			
Humidity	Dry		Medium	X	Humid	-		

Name of Visitors:	Company	Purpose of Visit
-		
 		

Work Description Summary	Labour	Equipment	Materials
Dredging canceled due to inability to	Miller		
deliver sediment to off load site.	Supervision:	Survey Boat .	Nil
Rebanco has limited delivery to	Randy Daggitt	Crew Boat	
2000 cubic yards per day.	Len Miller		
	Wes Yewell	STAND BY:	
Nie Erster der det in der det in der de	Rob Matheson	Dredge – Crystal	
No further dredging scheduled until		Gayle	i
Nov. 20, 2:00am		Tug - Norton Bay	
	<u>McAmis</u>	Tug – Loren M	
Construction hydrographic survey	Supervision:	Barge - Sand Island	
continues.	Craig Chartrand	Barge - Swan Island	
		\	
	Survey		
	John Hasall		
	Mike Doratti	1	,
	Geoff Methuen	·	
			i
•		· •	
			Ĭ
	i		
·	[·		ł
			1
	'	i	1
	<u> </u>		

Initials of Miller representative 2. ...





KING COUNTY DEPT. OF NATURAL RESOU

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

		Date						
					-			
V		41	D	T				
Year		ntn	Day	ins	spector			
2003	1]		20		rb			
	Day of the Week							
Sat	Sun Mo	n Tue	Wed	Thu	Fri			
				X				
		Weather	-					
Clear	PC	Overcast	Fo	g	Rain			
•		X			X			
		Temperatu	<u>ire</u>					
10-32	32-55	55-70	70-8	35	85+			
	X							

Construction Activities:

.Miller resumed dredging this morning. Crew on site at 2AM

This morning around 10AM one of the Indian Fisherman came up to the dock at our dredge site and said that our dredging crew had taken one of his net float and strobe light. Craig from McAmis (dredging sub-contractor) that was present stated in part that the fisherman had tied his float to the dredge anchor line buoy. The fisherman and Craig did not agreed on just exactly happened and the fisherman became upset and started to cuss and said that they own him a new bouy and strobe light. Craig did not agreed. The fisherman said that he would get hold of his lawyer and left in his boat.

Craig informed me that the fisherman cut his locate buoy to one of their anchors and they had to stop work to relocate there anchor as they needed to move it to reposition the barged for dredging.

Craig said that they lost 3 hours of dredging while they were working on finding and relocating their anchor.

Dan Gravning (EPA) on site this morning at the dredge site to watch the dredging activities. Due to concerns that during dredging activities crew was overfilling the bucket and spoils were spilling out and falling back into the water causing resuspension of contaminate back into the river which could carry up or down the river and settle in non contaminated areas.

Dan Gravning witness overfilled buckets and noted

Informed Dan that KC has talked to Miller about their dredging operation on Tuesday

Ukwenga Oleru Project Representative (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

	Dredge- Crystal Gayle Tug- Norton Bay Tug-Loren M Barges Sand Island/ Swan Island Survey Boat Crew Boat	1- Supervisor 3- Dredge Crew 2-Tug crew 2- Survey Crew
Miscellaneous:		
Safety/Accidents:		
Problems Encountered &		· · · · · · · · · · · · · · · · · · ·
Resolutions:	1	
Test Conducted:		
Work Rejected:		
Instructions Given to		
Contractor & Changes	1	
Initiated:		
Visitors to Site		
Equipment Used	1	
<u> </u>		

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	November 20, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First / Second					Х		

<u>Weather</u>	Clear	Х	Overcast		Foa	X	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	X	Moderate	_	High			070,00
Humidity	Dry		Medium	X	Humid	-		

Name of Visitors:	Company	Purpose of Visit
		

Work Description Summary	Labour	Equipment	Materials
Dredging resumed Area B, Stn.	Miller		
12+40 to 13+39, offsets +40 to +41	Supervision:	Survey Boat	Nil
Shifted over to 08+16, offset +62	Tom Johnson	Crew Boat	
	Randy Daggitt	Dredge – Crystal	
_	Len Miller	Gayle	
Construction hydrographic survey	Wes Yewell	Tug – Norton Bay	
continues.	Rob Matheson	Tug – Loren M	
•		Barge - Sand Island	
Norton Bay tug delivered Sand		Barge - Swan Island	
Island to Terminal 25 at 09:30	<u>McAmis</u>		
island to Tenninal 25 at 09.50	Supervision:		
	Craig Chartrand		
			}
	Sumas.	İ	İ
•	Survey John Hasall		İ
	Mike Doratti		
	Geoff Methuen		
	Geon Wethden		
		İ	
	-		
	İ		
		· ·	
	1]	

Initials of Miller representative 2.77





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	Mo	onth	Day	Ins	pector
2003	11		25		rb
	j	Day of the V	Week		
Sat	Sun Mo	n Tue	Wed	Thu	Fri
		х			
		Weathe			
		17 Cathe	'-		
Clear	PC	Overcas	t Fo	σ	Rain
0.000	10			5	Mani
		X			
		<u>Temperat</u>	<u>ure</u>		
10-32	32-55	55-70	70-8	35	85+
	X				

Date

Construction Activities:	their environmental Bucket which is Crew then stopped dredging and wor	at 6PM. Today crew change the dredge bucket over to a 18 cy bucket. Crew filled Sand Island barge by 10 PM. It is not the bucket welding up around the mesh screens are we started dredging again at noon today filling the Swan
	Dredge- Crystal Gayle	1- Supervisor
	Tug- Norton Bay	3- Dredge Crew
	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2-Tug crew 2- Survey Crew
	Survey Boat	2- Survey Crew
	Crew Boat	•
Miscellaneous:	CION Boat	
Safety/Accidents:		·
Problems Encountered &		
Resolutions:	1	
Test Conducted:		
Work Rejected:		
Instructions Given to		
Contractor & Changes		
Initiated:		
Visitors to Site		

Ukwenga Oleru Project Representative (Date)

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	November 25, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First / Second			Х				

Weather	Clear	X	Overcast		Fog	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69	70-85	
Wind	Calm		Moderate		High	70-05	Over 85
Humidity	Dry		Medium	X	Humid		

Name of Visitors:	Company	Purpose of Visit
	'	

Work Description Summary	Labour	Equipment	Materials
Instructed by King County to confine dredging to daytime shifts only. Resumed dredging Area B. Stn. 09+54 to 11+54, offsets +64 to +74.	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island	Nil
Trial use of environmental bucket to determine if water quality would improve.	McAmis Dredge Crew: Del Thompson Steve Barnes	Barge – Swan Island	
Construction hydrographic survey continues.	Fred Long Tug Crew: Brian Bammer		
Norton Bay Tug delivered Sand Island to Pier 25 at 11:15	Joe Vitaljic		
Norton Bay Tug delivered Swan Island to Pier 25 at 17:08	Survey John Hasall Mike Doratti		
Began dredging: 05:50			
Finished dredging: 15:30			





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	1	Ionth		D	T	
	•	1011111		Day	In:	pector
2003	3 11			26		rb
		Day of	the W	<u>'eek</u>		
Sat	Sun M	1on '	Tue	Wed	Thu	Fri
				Х		
		w	eather			
Clear	PC	Ove	ercast	Fog	3	Rain
			X			
		Tem	peratu	re		
10-32	32-55	5 5	5-70		5	85+
	\mathbf{X}					

Date

Construction Activities:	Crew on site this afternoon at 2PM. Crew changed out the dredge bucket from the Environmental Bucket back to the rock bucket. Crew started dredging today at approx. 2:40 PM. Crew slow downed dredging today at the request of KC from approx 4 hours per barge to approx 8 hours per barge. This is to try and minimize the turbidity during dredging operations. Crew dredge from 2:40PM (11-26) to approx 1AM (11-27).					
		•				
	Dredge- Crystal Gayle	1- Supervisor				
i	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M	2-Tug crew				
	Barges Sand Island/ Swan Island	2- Survey Crew				
	Survey Boat					
	Crew Boat					
Miscellaneous:		******				
Safety/Accidents:						
Problems Encountered &		W- W				
Resolutions:						
Test Conducted:						
Work Rejected:						
Instructions Given to						
Contractor & Changes						
Initiated:						
Visitors to Site						

UKU 7Z/15
Ukwenga Oleru Project Representative (Date)



Date Work Performed:	November 26, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat	}
Shift:	First				Х			-	

Weather	Clear	X Overcast	Foa	Rain	Coon
Temperature (°F)	Up to 32	X 32-50	51-69	70-85	Snow
Wind	Calm	X Moderate	High	70-65	Over 85
Humidity	Dry	Medium	X Humid		

Name of Visitors: Company Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
	Miller		
Continued dredging Area B. Stn.	Supervision:	Survey Boat	Nil
11+54 to 12+60, offsets +74 to + 87.	Tom Johnson	Crew Boat	'*''
7. 5 1 to 12 100, onocta 174 to 1 07.	Randy Daggitt	Dredge - Crystal	
	Len Miller	Gayle	
Shut down Nov. 27, 28, 29 for	Wes Yewell	Tug – Norton Bay	
Thanksgiving holiday.	Rob Matheson	Tug – Loren M	
3 3	, individuos in	Barge – Sand Island	1
		Barge – Swan Island	1
Continued construction	McAmis	Daige - Swari Island	
hydrographic survey.	Dredge Crew:		
	Del Thompson	1	
Nama Da Taran Da Arii	Steve Barnes		
Norton Bay Tug delivered Sand 11	Fred Long		
Island to Pier 25 at 02:00 (Nov 27)	1 red Long	i]
	Tug Crew:		
Began dredging: 14:40	Brian Bammer		
	Joe Vitaljic	ĺ	
Finished dredging: 24:00	1		Ì
	Survey		
	John Hasall	1	
	Mike Doratti	·	
]		
		•	
			1
	·		1

Initials of Miller representative

B.201





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Yea	r	Mon	th	Day	In:	spector
2003	3 1	2		1		rb
		Da	y of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
		X				
			Weather	-		
Clear	P	C	Overcast	Fo	g	Rain
			Х			
		7	Temperatu	ıre		
10-32	32	-55	55-70	 70-8	35	85+
	-	X				

Date

Construction Activities:	.There was no work done today. No work due to offload facility issues				
	Dredge- Crystal Gayle	1- Supervisor			
	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
	Barges Sand Island/ Swan Island	2- Survey Crew			
	Survey Boat Crew Boat	·			
Miscellaneous:	Cicw Boat				
Safety/Accidents:					
Problems Encountered &					
Resolutions:					
Test Conducted:					
Work Rejected:					
Instructions Given to					
Contractor & Changes					
Initiated:					
Visitors to Site	<u> </u>				

Ukwenga Oleru Project Representative (Date)

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 1, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First / Second		Х					

Weather	Clear	Х	Overcast		Fog	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69	70-85	Over 85
Wind	Calm	X	Moderate		High	-	
Humidity	Dry		Medium	X	Humid		

Name of Visitors:	Company	Purpose of Visit	

Work Description Summary	Labour	Equipment	Materials
No dredging. On stand-by until	Miller	···	
Terminal 25 transfer site is ready to	Supervision:	Survey Boat	Nil
take more dredgate.	Tom Johnson	Crew Boat	1
	Wes Yewell		
Continued construction	Rob Matheson	STAND BY:	
	.	Dredge – Crystal	1
hydrographic survey.	ľ	Gayle	
	1 .	Tug – Norton Bay	
		Tug – Loren M	
	Survey	Barge – Sand Island	}
	John Hasall	Barge – Swan Island	
	Mike Doratti		
			1
			{
	1		
			1
			•
		·	
	· ·		
		1	
	1		

Initials of Miller representative

B. 201





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r M	onth	Day	Ins	pector			
2003	12		2		rb			
	Day of the Week							
Sat	Sun M	on Tue	Wed	Thu	Fri			
		Х						
		Weath	<u>er</u>					
			_					
Clear	PC	Overcas	st Fo	g	Rain			
	X							
		Tempera	ture					
10-32	32-55	55-70		85	85+			
	X	20 .0			-			

Date

Construction Activities.	internal battery went dead and they I it back up to 100%. Dredge until approx 9:30AM and shu Crew repaired GPS system and resur Crew stopped at 12:20PM today as the vessel traffic. Crew resume dredging	rew had a problem with their GPS system. Apparently the ost some of their programs. Crew working on GPS to get ut down while crew worked on the GPS system. ned dredging at 11:04AM hey had to pull their barge out of the way to allow for
	Dredge- Crystal Gayle	1- Supervisor
	Tug- Norton Bay	3- Dredge Crew
	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island Survey Boat	2- Survey Crew
	Crew Boat	
Miscellaneous:		
Safety/Accidents:	-	
Problems Encountered &		
Resolutions:		
Test Conducted:	KC lab on site to take water test. Cre	w tested flood and ebb tide today
		

Ukwenga Oleru Project Representative (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Work Rejected:			
Instructions Given to			
Contractor & Changes			
Initiated:			
Visitors to Site	3 (NOAA) on site Colin Wa	gonner	
	3 (DOE) on site Rick Huey		
Equipment Used	1		
		•	
	1	•	
	<u></u>		
	1		



QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 2, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First			Х				

Weather	Clear	Х	Overcast		Fog	X	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	X	Moderate		High	_		Over 00
Humidity	Dry		Medium	X	Humid	_		

Name of Visitors:	Company	Purpose of Visit	
			—
	 		

Work Description Summary	Labour	Equipment	Materials
Continued dredging Area B. Stn. 12+67 to 12+97, offsets +90 to +93. Shifted to 08+27 to 08+90, offsets +90 to +112 Continued construction hydrographic survey. Norton Bay Tug delivered Sand Island to Pier 25 at 20:00 Began dredging: 7:00 Finished dredging: 19:15	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson McAmis Dredge Crew: Del Thompson Steve Barnes Fred Long Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko Survey John Hasall Mike Doratti	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island Barge – Swan Island	Nil

Initials of Miller representative

6.m.





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting

TIME WORK STARTED: TIME WORK STOPPED

3.7								
Year	Mor	ıtn	Day	Jn:	spector			
2003	2003 12		3		гb			
Day of the Week								
Sat S	un Mor	1 Tue	Wed	Thu	Fri			
			х					
		Weather	•					
			•					
Clear	PC	Overcast	Fo	g	Rain			
		Х	,					
		<u>Temperati</u>	<u>ire</u>					
10-32	32-55	55-70	70-8	35	85+			
	Х							

Date

KC lab on site for water testing. Cre	w tested on flood and ebb tide today						
KC lab on site for water testing. Cre	w tested on flood and ebb tide today						
· ·							
Crew Boat							
Survey Boat							
Barges Sand Island/ Swan Island	2- Survey Crew						
Tug-Loren M	2-Tug crew						
Tug- Norton Bay	3- Dredge Crew						
Dredge- Crystal Gayle	1- Supervisor						
See Attached Miller report							
Miller surveyor crew on site this afte	rnoon to survey area B						
	the downstream inshore area. Crew dredged today until						
Crew moved downstream to area A. Crew had to move/adjust barge anchors. Crew set up started dredging (2PM) in area A at the downstream inshore area. Crew dredged today u							
area. Crew completed to date dredgi							
1	oading the Swan Island working in area B in the outboard						
	start dredging until 8:17AM. Crew I area. Crew completed to date dredging Crew moved downstream to area A. started dredging (2PM) in area A at 6pm today. Miller surveyor crew on site this after See Attached Miller report Dredge- Crystal Gayle Tug- Norton Bay Tug-Loren M Barges Sand Island/ Swan Island						

Ukwenga Oleru Project Representative (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Contractor & Changes Initiated:	
Visitors to Site	Colin Wagoner (NOAA)
Equipment Used	



Date Work Performed:	December 3, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First				Х			

Weather	Clear	X	Overcast	Fog	Rain	Snow
Temperature (°F)	Up to 32	X	32-50	51-69	70-85	Over 85
Wind	Calm	X	Moderate	High	<u> </u>	
Humidity	Dry		Medium	X Humid		

Name of Visitors:	Company	Purpose of Visit
	· · · · · · · · · · · · · · · · · · ·	

Work Description Summary	Labour	Equipment	Materials
Continued dredging Area B. Stn. 10+57 to 11+67, offsets +101 to +109. Shifted to dredging Area A. Stn. 00+82 to 01+13, offsets -64 to -63	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island	Nil
Continued construction hydrographic survey.	McAmis Dredge Crew: Del Thompson	Barge – Swan Island	
Norton Bay Tug delivered Swan Island to Pier 25 at 18:00	Steve Barnes Fred Long		
Began dredging: 08:16 Finished dredging: 17:30	Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko		
	Survey John Hasall Mike Doratti		

Initials of Miller representative _

A.M





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Dumamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Hartford Contracting


TIME WORK STARTED: TIME WORK STOPPED

Yea	r Me	onth	Day	Ins	spector	
2003	3 12		4		rb	
	Day of the Week					
Sat	Sun Mo	n Tue	Wed	Thu	Fri	
				X		
		Weathe	r			
			-			
Clear	PC	Overcast	For	g	Rain	
		. X	·	_		
		Temperat	ure			
10-32	32-55	55-70	70-8	1 5	85+	
10 32	X	55 70	, 5-0		5 5.	

Date

Construction Activities:		ew performed maintenance on euipment first thing and Crew completed dredging to at 3:15 pm and sent the
Miscellaneous:	Dredge- Crystal Gayle Tug- Norton Bay Tug-Loren M Barges Sand Island/ Swan Island Survey Boat Crew Boat	1- Supervisor 3- Dredge Crew 2-Tug crew 2- Survey Crew
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:	K C lab on site to take water samples at	flood tide
Work Rejected:		
Instructions Given to		·
Contractor & Changes		
Initiated:		
Visitors to Site	ColinWagoner (NOAA)	
	Patrica Miller (USACE)	

Ukwenga Oleru Project Representative (Date)



REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

	Kym Takasaki (USACE)
Equipment Used	1
	·

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 4, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First					X		

Weather	Clear	X	Overcast		Fog	Х	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	Х	Moderate		High	_		
Humidity	Dry		Medium	X	Humid	_		

Name of Visitors:	Company	Purpose of Visit
	 	

Work Description Summary	Labour	Equipment	Materials .
Work Description Summary Continued dredging Area A. Stn. 00+95 to 02+74, offsets -60 to -56. Continued construction hydrographic survey. Norton Bay Tug delivered Sand Island to Pier 25 at 16:30 Began dredging: 06:35 Finished dredging: 15:00	Miller Supervision; Randy Daggitt Len Miller Wes Yewell Rob Matheson McAmis Supervision Craig Chartrand Dredge Crew: Del Thompson Steve Barnes Fred Long Tug Crew; Brian Bammer	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island Barge – Swan Island	Materials .
·			

Initials of Miller representative







KING COUNTY **DEPT. OF NATURAL RESOURCES** WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish/ Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Yea 200		Mont	h ·	Day 5	In	spector rb
		Day	of the W	/eek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						х
			Weather	,		
Clear	P	C (Overcast	Fog	g	Rain
. •	•					x
		<u>T</u>	emperatu	<u>re</u>		
10-32	. 32	-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:	Crew on site this morning to resume dredging in area A						
	Crew started dredging at 6:25AM. Crew stopped at approx 10:15AM for maintenance.						
	Crew resume dredging at 11:30AM.						
	Len (Miller) asked about the discharge pipes at the siphon pipe structure. He noted turbidity coming out the end of pipe (cso/sd?) They are dredging downstream of the pipe and was concerned that this flow might affect our testing. Inspected siphon pipe structure and found a plum of dirty looking water in front of structure which appears to be coming from structure						
	possibly from CSO/SD pipe at structu	ıre.					
	Stopped dredging at 12:23PM with a	full barge (Swan Island)					
	Dredge- Crystal Gayle	I - Supervisor					
	Tug- Norton Bay	3- Dredge Crew					
	Tug-Loren M	2-Tug crew					
	Barges Sand Island/ Swan Island	2- Survey Crew					
	Survey Boat						
	Crew Boat						
Miscellaneous:							
Safety/Accidents:							
Problems Encountered & Resolutions:							
Test Conducted:	KC Lab on site for water testing at ap activities were complete.	rox 12:40PM. Crew conducted test after dredging					
Work Rejected:							
Instructions Given to							
Contractor & Changes							
Initiated:							
Visitors to Site	Kym Takasaki (USACE) taking photo	OS					

Ukwenga Oleru Project Representative (Date)

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 5, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat	Ì
Shift:	First						Х		

Weather	Clear	Х	Overcast		Foa	Y	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69	^	70-85	
Wind	Calm	X	Moderate		High		70-65	Over 85
Humidity	Dry		Medium	X	Humid	_		

Name of Visitors: Company Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
	Miller		
Continued dredging Area A. Stn.	Supervision:	Survey Boat	Nil
02+74 to 03+70, offsets -67 to -57.	Randy Daggitt	Crew Boat	
	Len Miller	Dredge – Crystal	
Continued construction	Wes Yewell	Gayle	Ì
Continued construction	Rob Matheson	Tug - Norton Bay	
hydrographic survey.		Tug – Loren M	
		Barge - Sand Island	1
Norton Bay Tug delivered Swan	McAmis	Barge – Swan Island	
Island to Pier 25 at 16:00	Supervision		
	Craig Chartrand		İ
_	Dredge Crew:		
Began dredging: 06:15	Del Thompson Steve Barnes		1
Finished dredging: 12:40	Fred Long		
5 5	Fred Long		
	Tug Crew:		
	Brian Bammer		
	Joe Vitaljic		j
	Brian Polinkas	- 1	-
	Ted Yanko	1	
	Survey		
	John Hasall	ļ	i
	Mike Doratti		
		·	
	1		1

Initials of Miller representative

6.m





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r M	onth	Day	Ins	pector
2003	12		8		rb
		Day of the V	<u>Week</u>		
Sat	Sun M	on Tue	Wed	Thu	Fri
	y	ζ			
		Weathe	<u>r</u>		
Clear	PC	Overcas	t Fo	g	Rain
		X			
		Temperat	<u>ure</u>		
10-32	32-55	55-70	70-8	35	85+
	X				

Date

Construction Activities:

.Crew on site this morning at 6AM. Crew working on maintenance.

Crew started dredging in area A at 6:30 AM this morning.

Stopped dredging at 9:30AM maintenance

Resume at 10AM

Stopped at 11:06AM maintenance

Resumed 12 noon

Noted 3 full buckets (12:10PM), however crew did not stop. Contacted Miller and they stopped for 5 minutes. This was after 4th bucket (4th bucket was not overfilled).

Crew dredged up a large chain at approx 12:40PM and dragged it around a bit and brought it up on the Loren M. This is approx the same time KC lab was starting their water test Noted today that crew is getting quit a few overfilled bucket (2 in 4)

Contacted Len (Miller) and told him that we were getting to many overfilled bucket and he needed to do something to stop getting overfilled buckets.

Contacted Ukwenga Oleru and informed him of the dredging activities.

Crew completed filling Sand Island at 2PM and left for T-25

Sand Island was filled in approx 5 hours today

Crew brought back the Swan Island at 4PM and started dredging at 4:05 PM

Did not witness any full buckets while filling the Swan Island

Crew stopped dredging at 5:44PM

Dredge- Crystal Gayle Tug- Norton Bay 1- Supervisor

3- Dredge Crew

() 12/15/03 Ukwenga Olem Project Representative (Da

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2- Survey Crew
	Survey Boat	
	Crew Boat	·
Miscellaneous:		
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:	KC Lab on site today to take water sar	mples crew sample flood and ebb tides today
Work Rejected:		
Instructions Given to		
Contractor & Changes		
Initiated:		
Visitors to Site	Colin Wagoner (NOAA)	
	BJ (DRC) on site at approx 12:25 PM	(did not check in at the office) She report to UO that she
	saw 8 out of 10 buckets were overfille	rd
Equipment Used	1	
		<u> </u>



Date Work Performed:	December 8, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First		Х					

Weather	Clear	X Overcast	Fog	Rain	Snow
Temperature (°F)	Up to 32	X 32-50	51-69	70-85	Over 85
Wind	Calm	X Moderate	High	7000	Over 65
Humidity	Dry	Medium	X Humid		

Name of Visitors:	Company	Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
	Miller		
Continued dredging Area A. Stn. 03+70 to 04+98, offsets -50 to -59.	Supervision: Randy Daggitt	Survey Boat Crew Boat	Nil
	Len Miller Wes Yewell	Dredge – Crystal	
Continued construction	Rob Matheson	Gayle Tug – Norton Bay	
hydrographic survey.		Tug – Loren M Barge – Sand Island	
Norton Bay Tug delivered Sand	<u>McAmis</u>	Barge – Swan Island	
Island to Pier 25 at 15:00	Supervision Craig Chartrand		
	Dredge Crew:		
Began dredging: 06:30	Del Thompson Steve Barnes		
Finished dredging: 17:30	Fred Long		
•	Tug Crew:		
	Brian Bammer		
	Joe Vitaljic Brian Polinkas		
	Ted Yanko		
	Survey		
	John Hasall Mike Doratti		
	Winke Dorate		

Initials of Miller representative _

8.2m





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT NO.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		Dat			
Į.					
ļ					
Year	r N	Aonth	Day	Ins	pector
2003	3 12		9		rb
		Day of the	e Week		
Sat	Sun M	Aon Tue	Wed	Thu	Fri
		Х			
		Weatl	her		
Clear	PC	Overca	ast Fo)g	Rain
<u> </u>	x			-	
	λ				
		Temper			
10-32	32-5	5 55-70	0 70-	85	85+
	X				

Date

Construction Activities:

.Crew on site this morning at 6PM

Crew started dredging at 6:25AM filling the Swan Island.

Crew appears to be dredging slower then yesterday

It was reported to me by Len (Miller) that when they retrieved there barge (Swan Island) from T-25 on 12-8-03 (afternoon) the barge received damage. According to Len the aprons that span the dock to the barge rest on the rail and when they pulled away the apron slammed down on the barge lip and damaged the barge.

Miller Survey crew on site this morning (approx. 9:15AM) to survey area B

Len (Miller) notified me at approx. 10:14AM that they have noticed a shin on the surface of the water around the dredge. He said that will notify the Coast Guard and EPA.

Crew stopped dredging at 10:20AM due to the presents of the shin

Crew stocking up on extra oil containment boom material and taking o barge

Len (Miller) asked direction from KC on how to proceed as they seen the oil shin as a differing site condition. Len informed me that there crew is on standby until direction from KC Miller (Len) informed that the Coast Guard told then it was okay to continue to dredge with caution. Informed Tom Dean and he instructed me to direct Miller to go ahead and resume dredging at 12:20PM. Due to a shin in the water on the barge Miller will not fill the barge completely allowing water in the barge to go through the dewatering stand pipes. Miller will take partially filled barge to T-25. This barge will probably have excess free water which will need to be handled at T-25. Informed Len (Miller) of how to proceed and gave them the above stated direction.

Crew resumed dredging at 1:05 PM Stopped Dredging at 1:30 PM. Barge was approx. 90% full. Barge was delivered to T-25 around 6PM

Rick Huey (DOE) called and asked about our shining that was reported to DOE and Coast Guard

Informed Him that Coast Guard gave us the go ahead to dredge with caution and explained briefly Miller's spill response plan. He seemed to be okay in what we did.

Crew moved their anchors for repositioning for dredging tomorrow.

Len (Miller) Informed me that he talk to Steve (Wilder) and said that Miller would not br able to get their barge from T-25 until 6PM tonight due to offloading issues.

Randail Brunke, Construction Inspector (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

·		
1		
		•
	·	
	Dredge- Crystal Gayle	1- Supervisor
·	Tug- Norton Bay	3- Dredge Crew
İ	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2- Survey Crew
	Survey Boat	L Survey Siew
	Crew Boat	į
Miscellaneous:		sure boat was in the dredging area and appeared to be
	taking pictures/videos	
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:	KC lab on site to perform water testing	g. Crew only tested once today due to the stoppage
	caused by the oil shin, not having eno	ough dredge time
Work Rejected:		
Instructions Given to		
Contractor & Changes		
Initiated:		
Visitors to Site	Patricia Miller, Kym Takasaki, Bob P	arry all form USACE
Equipment Used	1	
L	<u> </u>	

Initials of Miller representative _____

1

QC 3D - MISCELLANEOUS CORRECTIVE ACTION REPORTS DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date of Incident:	December 9, 2003	
Superintendent:	Len Miller	1
	<u> </u>	J
1. CAUSE FO	OR CORRECTIVE ACTION	
While dredging in Area A	, approximate station 04+50, of	fset -60', a oil sheen was observed on the
water surface at 10:00 A	M. The sheen was approximate	ely 400' long and 40' wide. The substance
in the water originated from	om the dredged sediment or pos	ssibly an adjacent storm sewer outfall.
· · · · · · · · · · · · · · · · · · ·	·	
2 ODEDATIO		
2. OPERATIC	NAL RESPONSE	
Stopped dredging at	approximately 10:00 AM.	
	sheen on the river with a oil abs	orbant bassa
		location. Partially filled barge was sent
to Pier 25. Rebanco	to remove and treat water contr	ained in hopper barge. Notified US Coast
Guard of intention to	restart	anied in hopper barge. Notified US Coast
Relocated to new are		
The section to flow and	a war restribute.	
NOTIFICATIONS		
King County: Project Rep	Randy Brunke	
US Coast Guard: referen		
Washington State DOE:		
Transfer diata boz.	<u> </u>	· ·
3. CORRECTI	VE ACTION TAKEN	
a Poloostad to now with	NAPH LAW	
Nelocated to new cut	. Will avoid the area where she	en was created until advised by King County.
·		
•		

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 9, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First	†	<u> </u>	Х			 	Cat

<u>Weather</u>	Clear	X Overcast	Fog	Rain	•
Temperature (°F)	Up to 32	X 32-50			Snow
Wind			51-69	70-85	Over 85
*	Calm	X Moderate	High		
Humidity	Dry	Medium	X Humid		

Name of Visitors:	Company	Purpose of Visit	

Work Description Summary	Labour	Equipment	Materials
	Miller		
Continued dredging Area A. Stn.	Supervision:	Survey Boat	Nil
04+98 to 05+00, offsets -55 to -59.	Tom Johnson	Crew Boat	1
	Randy Daggitt	Dredge – Crystal	
Continued construction	Len Miller	Gayle	
hydrographic survey.	Wes Yewell	Tug - Norton Bay	1
my arographic survey.	Rob Matheson	Tug – Loren M	1
	·	Barge – Sand Island	ĺ
Norton Bay Tug delivered Swan	<u>McAmis</u>	Barge - Swan Island	
Island to Pier 25 at 15:00	Supervision		
	Craig Chartrand		
Began dredging: 06:20	Dredge Crew:		
	Del Thompson		
Finished dredging: 13:40	Steve Barnes		
	Fred Long		
	Tug Crew:		
	Brian Bammer		
	Joe Vitaljic		
	Brian Polinkas		ſ .
	Ted Yanko	1	1
	Sumou		
	Survey John Hasall		
	Mike Doratti		ļ
	Wilke Doratti		
			ł

Initials of Miller representative _

6.20





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

!							
Year	r ì	Month		Day	In	spector	
2003	3 12			10		rb	
Day of the Week							
Sat	Sun 1	Mon	Tue	Wed	Thu	Fri	
				X			
		2	Weathe	<u>:r</u>			
Clear	PC	C	vercas	t Fo	g	Rain	
			X			X	
	<u>Temperature</u>						
10-32	32-5	5	55-70	70-8	35	85+	
	X						

Date

Construction Activities:	Crew on site this morning at 6PM							
	Crew started dredging (Sand Island)	at 6:25AM						
	Crew completed Dredging the Sand	Island at 1:50PM						
		Ailler's sub that the Sand Island was brought back from						
		T-25 with approx. 375 c.y of material still in barge. They went to T-25 at 6PM last night and						
	Miller surveyors on site today to sur	vev dredging						
		1:55PM. Crew started dredging for the Swan Island at						
	2:06 PM. Crew stopped at 3PM for	naintenance. Crew resumed dredging at 4:10PM						
	Crew stopped dredging at 6:36PM ar	d will resume filling Swan Island in the morning.						
	Dredge- Crystal Gayle	1- Supervisor						
	Tug- Norton Bay	3- Dredge Crew						
	Tug-Loren M	2-Tug crew						
	Barges Sand Island/ Swan Island	2- Survey Crew						
	Survey Boat	2- but vey ciew						
	Crew Boat							
Miscellaneous:								
Safety/Accidents:								
Problems Encountered &								
Resolutions:								
Test Conducted:	KC lab on site to take water samples.	Tested this on ebb tide. Was unable to test this						
	afternoon's flood tide because dredgi							

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Work Rejected:	
Instructions Given to	
Contractor & Changes	•
Initiated:	
Visitors to Site	BJ Cummings (DRC) was on site this morning but did not check in at the office Patricia Miller and Dennis Mekker (USACE)
Equipment Used	

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 10, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First				Х			

<u>Weather</u>	Clear	X Overcast	Foa	X Rain	Snow
Temperature (°F)	Up to 32	X 32-50	51-69	70-85	Over 85
Wind	Calm	X Moderate	High		
Humidity	Dry	Medium	X Humid	_	

Name of Visitors:	Company	Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
Resumed dredging at NW corner of Area A. Stn. 00+70 to 20+05, offsets7 to -8. Continued construction hydrographic survey. Norton Bay Tug delivered Sand Island to Pier 25 at 12:00 Began dredging: 06:20 Finished dredging: 18:45	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson McAmis Supervision Craig Chartrand Dredge Crew: Del Thompson Steve Barnes Fred Long Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko Survey John Hasall Mike Doratti	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island Barge – Swan Island	Nil

Initials of Miller representative ___

R21





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

		Date					
ļ							
Year	- M	onth	Day	Ins	pector		
2003	12		11		rb		
	Day of the Week						
Sat	Sun M	on Tue	Wed	Thu	Fri		
				X			
		Weather					
Clear	PC	Overcast	Fog		Rain		
		Х			Х		
		Temperatu	ire				
10-32	32-55	55-70		5	85+		
l	Х						

Construction Activities:	Crew on site at 6AM this morning. Crew is down this morning working on the crane brake system Crew resumed dredging for the Swan Island at 8:04AM Stopped dredging 9:32 AM. The operator had to leave the barge and leave the site. Resumed dredging at 9:45AM. Crew completed filling the Swan Island at 11:11AM Crew changing out barges and maintenance; began swapping barges at 11:18AM Resumed Dredging area A with the Sand Island at 12:00PM crew was down for 20Min around 2:30PM. Stopped at 5:38PM. Resumed at 6:04PM Crew stopped at 7:47PM					
	Dredge- Crystal Gayle	1- Supervisor				
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M	2-Tug crew				
	Barges Sand Island/ Swan Island	2- Survey Crew				
}	Survey Boat					
	Crew Boat					
	A WDFW research vessel worked in	the vicinity of the dredge after (9:15AM).				
	And talked to crew about something					
Safety/Accidents:						
Problems Encountered & Resolutions:						
Test Conducted:	KC lab on site to do water test at 9:20	AM. Crew was able to test before the crew ha to shut				
	down but not by much. Crew tested e					
Work Rejected:						
Instructions Given to						

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

MILLER CONTRACTING INC

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 11, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First					X		<u> </u>

Weather	Clear	X Overcast	Fog	X Rain	Snow
Temperature (°F)	Up to 32	X 32-50	51-69	70-85	Over 85
Wind	Calm	X Moderate	High		•
Humidity	Dry	Medium	X Humid	_	

Name of Visitors:	Company	Purpose of Visit	
			

Work Description Summary	Labour	Equipment	Materials
Continued dredging at Stn. 02+05 to 03+62, offsets 5' to 6'. Continued construction hydrographic survey.	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island Barge – Swan Island	Nil
Norton Bay tug delivered Swan Island to Pier 25 at 12:30. Norton Bay tug delivered Sand Island to Pier 25 at 21:30	McAmis Supervision Craig Chartrand Dredge Crew: Del Thompson John Morgan Steve Jarrell	Barge Gran Gran	
	Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko		
	Survey John Hasall Mike Doratti		·

-63m





KING COUNTY DEPT. OF NATURAL RESOURCES

WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	Mor	nth	Day	Ins	spector			
2003	12		12		rb			
	Day of the Week							
Sat S	un Mor	n. Tue	Wed	Thu	Fri			
l L					X			
		Weather			•			
Clear	PC	Overcast	Fog	ž	Rain			
		x		•	X			
		Temperatu	<u>ire</u>					
10-32	32-55	55-70	70-8	5	85+			
	X							

Date

Construction Activities:	Crew on site at 6AM						
]	Crew started filling the Swan Island	Crew started filling the Swan Island with Area A dredge spoils at 6:35AM. Work is currently					
	between (Dredge Plan) app. sta. 4+00 to 7+00.						
		, oiling at 08:50AM. Inspection by contractor found					
Ì	critical damage to the main friction brakes. Dredging work did not resume until 2:50PM Crew completed dredging the Swan Island at 8:00PM						
	·	·					
		İ					
	Dredge- Crystal Gayle	1- Supervisor					
·	Tug- Norton Bay	3- Dredge Crew					
	Tug-Loren M	=					
		2-Tug crew					
	Barges Sand Island/ Swan Island	2- Survey Crew					
	Survey Boat						
	Crew Boat						
Miscellaneous:		·					
Safety/Accidents:							
Problems Encountered &							
Resolutions:		·					
Test Conducted:	KC lab on site this afternoon to take water test. Due to contractor being down this morning no						
	test was performed.						
Work Rejected:							
Instructions Given to							
Contractor & Changes	1						
Initiated:							
Initiated:							

UR Oleru Project Representative (Date)

Anolla

Randall Brunke, Construction Inspector (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

	Survey Boat	
	Crew Boat	
Miscellaneous:		
Safety/Accidents:		_
Problems Encountered &		
Resolutions:		
Test Conducted:	KC lab on site for testing today. Crew tested two times today.	
Work Rejected:		
Instructions Given to	Informed Len (Miller) that the Flood and ebb tide water quality test show reading above	
Contractor & Changes	maximum allowed and they needed to adjust dredging activities	
Initiated:		
Visitors to Site		
Equipment Used	1	

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 12, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First						Х	

Weather	Clear	Х	Overcast	Fog	Rain	Snow
Temperature (°F)	Up to 32	X	32-50	51-69	70-85	Over 85
Wind	Calm	X	Moderate	High		Over 05
Humidity	Dry		Medium	X Humid		

Name of Visitors: Company Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
	Miller	 	
Continued dredging at Area A. Stn.	Supervision:	Survey Boat	Nil
03+62 to 04+12, offsets 5' to 6'.	Tom Johnson	Crew Boat	
	Randy Daggitt	Dredge – Crystal	
Continued construction	Len Miller	Gayle	
hydrographic survey.	Wes Yewell Rob Matheson	Tug – Norton Bay	1
nyorographic survey.	Rob Matheson	Tug – Loren M Barge – Sand Island	İ
		Barge – Swan Island	
Norton Bay Tug delivered Swan	<u>McAmis</u>	Daige - Swall Island	
Island to Pier 25 at 21:00	Supervision		
	Craig Chartrand		
Began dredging: 06:15	<u>Dredge Crew:</u>		
Finished dredging: 20:10	Del Thompson		
Finished diedging. 20, 10	Steve Jarrell		1
	Tug Crew:		1
	Brian Bammer		
	Joe Vitaljic		
•	Brian Polinkas		1
	Ted Yanko	1	ł
	Survey		}
	John Hasall Mike Doratti		}
•	WIIKE DOIALLI		1
			1
			1
		1	

Initials of Miller representative

6,27



REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish/ Diagonal Sedement Remediation

Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: 0600hrs. TIME WORK STOPPED: 1630hrs.

		Date	2					
Year	r N	lonth	Day	Ins	pector			
200	3 De	cember	13	Ke	ith N.			
İ	Day of the Week							
Sat	Sun M	lon Tue	Wed	Thu	Fri			
l x			,					
		Weath	er					
Clear	PC	Overca	is Fo	g	Rain			
		t		Ŭ				
ŀ		X			X			
ĺ		Ş			ı			
		<u>Tempera</u>						
10-32	32-55	55-7	0 70-	85	85+			
	X							

Construction Activities:	"Crystal Gayle" resumed short term dredging (barge Sand Island) where they left off in Area A yesterday at 0715hrs. "Crystal Gayle" began shifting anchors and moving S. to Area B after 0830hrs. (High tide @ 12.3' occurred during the move). Dredging work proceeded N. to S. in Area B (app. Dredge Plan start at sta. 9+00 to 10+00) began after 0924hrs. and stopped at 1010hrs. for a anchor shift to a position further offshore. Dredging resumed 1045hrs. and proceeded with only intermittent stops until 1315hrs. when "Crystal Gayle" anchors were shifted, and for routine maintenance work. Dredging resumed after 1405hrs. Dredging in Area B ended at 1520hrs. The "Crystal Gayle" then moved N. to Area A to end the work day at 1630hrs.
Miscellaneous:	
Safety/Accidents:	No work related accidents were reported to KC by the Contractor.
Problems Encountered &	This morning, the Contractor (Craig) reported onboard survey equipment (primarily the depth
Resolutions:	finder) was giving back "strange" readings. The surveyor arrived after 0720hrs. to troubleshoot
	the program. Dredging ceased around 0730hrs. while the surveyor worked on the program.
Test Conducted:	Ebb tide turbidity tests taken by KCEL after 1145hrs.
Work Rejected:	
Instructions Given to	No field directives were given to the Contractor this day.
Contractor & Changes	•
Initiated:	

Ukwenga Oleru, Project Representative (Date)

Keith Nordlund, Construction Inspector, 12/13/03



REPORT NUMBER: 1

CONTRACT NUMBER: #C33027C

Visitors to Site	Bob, KCEL; Tom Johnson, JJM; Ukwenga Oleru, KC					
Equipment/ Personnel	Dredge "Crystal Gayle" Tug "Norton Bay" Tug "Loren M" (2)Barges "Sand Island", "Swan Island" Survey Boat, Crew Boat	1- Supervisor 3- Dredge Crew 2-Tug crew 2- Survey Crew				

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 13, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First							X

Weather	Clear	X	Overcast		Fog	X	Rain	Snow
Temperature (°F)	Up to 32	X	32-50		51-69		70-85	Over 85
Wind	Calm	X	Moderate		High			
Humidity	Dry		Medium	X	Humid	-		

Name of visitors:	Company	Purpose of Visit
· · · · · · · · · · · · · · · · · · ·		

Work Description Summary	Labour	Equipment	Materials
Shifted back to Area B for cleanup of high spots. Dredging at Stn. 08+52 to 12+77, offsets 4' to 105'. Continued construction hydrographic survey.	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island	Nil
Began dredging: 09:15 Finished dredging: 15:10	McAmis Supervision Craig Chartrand Dredge Crew: Del Thompson Steve Jarrell	Barge – Swan Island	
	Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko		
	Survey John Hasall Mike Doratti		

Initials of Miller representative _____

RM





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	· Mo	onth	Day	Insp	ector
2003	12		15		rb
ŀ]	Day of the \	Veek		
Sat	Sun Mo	on Tue	Wed	Thu	Fri
	X	_			
	•	Weathe	r		
		<u> </u>	-		
Clear	PC	Overcast	Fog		Rain
ł	X				
		Temperate	1150		
10.22	22 55			_	05.
10-32	32-55	55-70	70-8	5	85+
1	X				

Date

Construction Activities:

.Crew on site this morning at 6AM

Crew started dredging for the Sand Island at 6:47AM. The Sand Island was used to dredge on Saturday the 13th to clean up area B. The barge had a lot of free water from Saturday's dredging as they had a lot of clean up passes.

Crew started today dredging the buffer zone between area A and area B

Crew stopped dredging at 9:25AM resume at 9:30AM

Barge has water almost up to the rail (5 to 6 inches) while still loading the barge. It appeared that they did something to one of their dewatering pipes and the water in the barge went down about a foot. Talked to Len from Miller and told him that we need to make sure that we do not spill water over the side of the rail and need to maintain our dewatering system to make sure we do not discharge untreated water back into the river.

Crew completed filling the Sand Island at 10:33AM and the Swan Island is on site to pull into position next to dredge. Crew also is greasing the rig at this time (11AM)

Sent Sand Island to T-25 at 11AM. Crew resume dredging at 12:05PM. Stopped for a short while to move the dredge S. to Area B. Resumed dredging at Contractor Survey indicated high spots from 12:25PM to 1:10PM. Crystal Gayle anchors were moved further South. Resumed dredging at 1:34PM. Contractor continued moving and spot contour dredging until app. 1800hrs. The work day ended near Dredge Plan Sta. 13+80.

Dredge- Crystal Gayle

Tug-Norton Bay Tug-Loren M

Barges Sand Island/ Swan Island

1- Supervisor

3- Dredge Crew

2-Tug crew

2- Survey Crew

TROLOVU 12/18/03
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

QC 3A - DAILY OPERATIONS INFORMATION DUWAMISH/DIAGONAL SEDIMENT REMEDIATION PROJECT

Date Work Performed:	December 15, 2003	Sun	Mon	Tue	Wed	Thu	Fri	Sat
Shift:	First		Х					

Weather	Clear	Х	Overcast		Fog	Rain	Cnau
Temperature (°F)	Up to 32	X	32-50		51-69	70-85	Snow
Wind	Calm	<u>X</u>	Moderate		High	70-65	Over 85
Humidity	Dry		Medium	X	Humid		

Name of Visitors: Company Purpose of Visit

Work Description Summary	Labour	Equipment	Materials
Shifted into Area A for to dredge buffer area between Area A and B. Dredging at Stn. 07+89 to 11+59. Continued construction hydrographic survey. Norton Bay tug delivered Sand Island to Pier 25 at 11:55.	Miller Supervision: Tom Johnson Randy Daggitt Len Miller Wes Yewell Rob Matheson McAmis Supervision Craig Chartrand Dredge Crew: Del Thompson	Survey Boat Crew Boat Dredge – Crystal Gayle Tug – Norton Bay Tug – Loren M Barge – Sand Island Barge – Swan Island	Nil
Began dredging: 06:45 Finished dredging: 18:15	Steve Jarrell Tug Crew: Brian Bammer Joe Vitaljic Brian Polinkas Ted Yanko		
	Survey John Hasall Mike Doratti		





KING COUNTY DEPT, OF NATURAL RESOU

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r Mo	onth	Day	Ins	pector
2003	3. 12		16		rb
		Day of the V	Veek		
Sat	Sun Me	on Tue	Wed	Thu	Fri
		X			
		Weather	<u>r</u>		
Clear	PC	Overcast	Fog	3	Rain
		Х			X
		Temperati	ure		
10-32	32-55	55-70	— 70-8	5	85+
	v			•	

Date

Construction Activities:	.Crew on site this morning at 6AM						
		van Island). Crew continue to dredge in area B inshore.					
		0AM and move to the buffer zone in area A. Miller will					
		hey are done. Crew resume dredging area A buffer zone					
	,	at 7:52AM. Crew stopped dredging at 9:35AM as the "Swan Island" was filled. The Sand sland was brought up to site and crew switched barges out to start filling the "Sand Island".					
ļ	,	in Area A (buffer zone) at 10:03AM. Work stopped to					
		redge bucket at 1050AM. "Crystal Gayle" resumed					
		dredging with only short pauses until 5:00PM, with the					
	,	dredging with only short pauses than 5.00PM. With the					
	filling of the "Sand Island".						
į							
		•					
	Dredge- Crystal Gayle	1- Supervisor					
	Tug- Norton Bay	3- Dredge Crew					
	Tug-Loren M	2-Tug crew					
	Barges Sand Island/ Swan Island	2- Survey Crew					
	Survey Boat	•					
	Crew Boat	•					
Miscellaneous:	Miller survey boat on site this mornin	g at 9:15AM to verify Substantial Completion of					
	dredging in Area B.						
Safety/Accidents:							
Problems Encountered &							
Resolutions:							
Test Conducted:	KC lab on site this morning at app. 8	30AM to take flood turbidity test. KC Ebb tide testing					
-	began at app. 1:30PM.						
	,						

Ukwenga Oleru Project Representative (Date)

(Randall Brunke, Construction Inspector (Date)

A STATE OF THE STA

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Work Rejected:				
Instructions Given to	Informed Miller that the field flood tide water quality test showed to	urbidity was 4.8 over for the		
Contractor & Changes	300 foot bottom and they need to adjust their dredging activities			
Initiated:				
Visitors to Site	Tom Johnson, Rob Matheson; JJM; Ukwenga Oleru, Pat Romber, F	ricilla Hackney		
Equipment Used	1			





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	· Mo	nth	Day	In	spector
2003	12		17		гb
	<u>r</u>	ay of the V	Veek		
Sat	Sun Mo	n Tue	Wed	Thu	Fri
			Х		
		Weather	r		
			_		
Clear	PC	Overcast	Fo	g	Rain
X sunny	,				
-		Temperati	ıre		
10-32	32-55	55-70.		35	85+
	X.				

Date

Construction Activities:	Crew on site this morning (6AM) to resume dreaging.						
	Crew started dredging (Swan Island)	Crew started dredging (Swan Island) at 6:36AM dredging the buffer zone in area A. Stopped					
	at 8:20AM to 8:35AM to repair the						
	At approx. 9:15 witnessed 3 full buc	kets. Crew stopped for 5 minutes /time out. This is when					
	lab was testing.						
	Stopped dredging at 9:45AM for maintenance. Resumed dredging at 10:17AM						
	3 overfilled bucket w/time out at 10	:55AM stopped.					
	Resumed from time out at 11:00AM						
	Stopped at 11:07AM as crew cleaned side of the Swan Island and to get sun glasses It is sunny						
		and ended with the completion of filling the "Swan Is." at					
	App. 1:54PM. "Sand Is." was still be						
		to start filling after Swan Island was filled crew had to					
	shut down dredging for the remainde	•					
	To date T-25 has received 4 full barg	ges as of end of Wednesday.					
	Dredge- Crystal Gayle	1- Supervisor					
	Tug- Norton Bay	3- Dredge Crew					
	Tug-Loren M	2-Tug crew					
	Barges Sand Island/ Swan Island	2- Survey Crew					
	Survey Boat	·					
	Crew Boat						
Miscellaneous:							
Safety/Accidents:							
Problems Encountered &							
·							

UROLL 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

Page 1 of 1

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Resolutions:	
Test Conducted:	KC lab on site water test (flood) at approx. 9AM; ebb tide testing began at app. 1:53PM.
Work Rejected:	
Instructions Given to Contractor & Changes Initiated:	
Visitors to Site	Kym Takasaki (USACE); Pat Romber, KC; Tom Johnson, JJM; Rep. from Duwamish Coalition
Equipment Used	





KING COUNTY DEPT. OF NATURAL RESOURCES

DEPT. OF NATURAL RESOURCES Wastewater Treatment Division

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

D	a	t	e	

Year	Mont	th	Day	Inspector
2003	12		18	rb
	Da	y of the V	Veek	
Sat	Sun Mon	Tue	Wed	Thu Fri
	•			X
		Weather	:	
Clear X	PC	Overcast	Fog	Rain
	<u>1</u>	emperatu	<u>re</u>	
10-32	32-55	55-70	70-85	5 85+
	Х			

Construction	Activities:

Crew on site this morning at 6AM

Crew started dredging (Sand Island) this morning at 6:40AM

Crew had 3 overfilled buckets and stopped for 5 minutes to adjust dredging operations (6:50AM)

Crew still having trouble getting overfilled buckets this morning. Talked to Craig (McAmis) and asked him to slow down and to not get the overfilled buckets Crew stopped for 5 minutes to try and adjust (8AM)

Crew had 3 overfilled buckets at 11:05AM and took a 5 minute time out. Dredging stopped at that time, resumed 11:35AM, and stopped again at 11:50AM. "Crystal Gayle" moved S. to Area B to remove high spots in the grade found after the Contractor's most recent survey. Area B dredging resumed at app. 12:49PM. and ended at app. 1:30PM. with the "Sand Island" full. The "Swan Island" was still being offloaded at Terminal 25 (Rabanco was apparently having trouble getting a train earlier). The Dredge crew ended work for the day after returning to Area A at app. 2:00PM. Due to the swan Island not being available (still be offloaded at T-25) no more dredging was done this day/shift

Dredge- Crystal Gayle

Tug-Norton Bay Tug-Loren M

Barges Sand Island/ Swan Island

Survey Boat Crew Boat 1- Supervisor

3- Dredge Crew

2-Tug crew

2- Survey Crew

Miscellaneous:

UKWenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

Page 1 of 1

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Safety/Accidents:	
Problems Encountered & Resolutions:	
Test Conducted:	KC lab on site to test 9AM Lab did not test the ebb tide today as crew was not dredging due to Swan Island not avilable.
Work Rejected:	
Instructions Given to Contractor & Changes Initiated:	
Visitors to Site	Bob Hamilton (KC) 9AM to take pictures/video Patty Miller (USACE) Colin Wagoner (NOAA) DRC out in private Boat
Equipment Used	





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

Inspector's Daily Construction Report

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Yea	ar	Month	ſ	Day	Ins	ector	
200)3	12		19	rb		
		<u>Day</u>	of the \	Veek			
Sat	Sun	Mon	Tue	Wed	Thu	Fri	
						X	
			Weathe	<u>r</u>			

Date

Clear	PC	Overcast	Fog	Rain
		X		
		Temperatur	<u>e</u>	
10-32	32-55	55-70	70-85	85+
	X			

Construction Activities:	"Crystal Gayle" crew on site this morning at 6AM. Crew started dredging in Area A this morning at 6:30AM on the barge "Sand Island". Crew has dredged up debris this morning (ie logs) Some of the debris was dredged during water quality testing (around 9:40AM). Dredging continued with occasional stops for "overloaded bucket" penalties until 11:40AM. New work on the site ended at app. 1:00PM. Rabanco was not done emptying the "Swan Island". Due to the cleanup sequencing the Contractor needed for the barges, "Sand Island" delivery to Terminal 25 was delayed.				
	Dredge- Crystal Gayle Tug- Norton Bay Pilot Boat Lowren M Barges Sand Island/ Swan Island Survey Boat	1- Supervisor 3- Dredge Crew 2-Tug crew 2- Survey Crew			
Miscellaneous:	Crew Boat Miller survey crew on site to survey the Area A Buffer Zone that has now been substantially completed (to a width of app. 100')				
Safety/Accidents:					
Problems Encountered & Resolutions:	At 11:40AM the Contractor stopped dredging to clear cable wrapped around the starboard prop. and shaft of the "Lowren M").				
Test Conducted:	KC lab on site this morning at 9:30AM testing flood tide				
Work Rejected:					
Instructions Given to Contractor & Changes Initiated:					

UN Olevn 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspected (Date)

Page 1 of 1

REPORT NUMBER: 050

CONTRACT NUMBER: #C83235C

Visitors to Site	Tom Johnson, JJM; Colin ?, Rudolphini;
Equipment Used	
1	
1	
}	
1	
ĺ	





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

				•	
Van	M.	4L	Davi		.4
Year		onth	Day	Insp	oector
2004	4 Janua	ary	7	rb	/KN
	1	Day of the	Week		
Sat	Sun Mo	on Tue	Wed	Thu	Fri
			x		
		Weathe	er		
			-		
Clear	PC	Overcas	t Fog	g I	Rain/
		X		5	snow
		<u>Temperat</u>	ure		
10-32	32-55	55-70	70-8	15	85+
am	pm				

Date

Construction Activities:	Dredge "Crystal Gayle" re-mobised to the site today at app. 11AM. The Contractor has been at another site in Tacoma, Wash. since 12-20-03.				
	Crew reset their tide gauge, and set working anchors for soil removal in Area "A". The				
	"Crystal Gayle" is working S. from app. Dredge Plan sta. 50+00, along the furthest lane out				
	from shore (toe of the excavation).	pp. Dredge Flan sta. 50 '00, along the furthest lane out			
	•	ng barge "Sand Island", and stopped at 1:20PM. Resume			
		s until the barge was filled at app. 10 PM.			
	Dredge- Crystal Gayle	1- Supervisor			
	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
	Barges Sand Island/ Swan Island	2- Survey Crew			
	Survey Boat				
	Crew Skiff	1			
Miscellaneous:	Barges Swan Island and Sand Island v	vere inspected by KC at Terminal 25 (app. 12:00-			
	12:45pm) in regards to a dewatering p	roblem reported by Wilder/Rabanco during cleanup			
ļ	(12/19-20/03). Both "belly dump" style barges had been recently cleaned up by others. The				
	inspector observed water ponded directly above the barge's keel jaws (with bulb compression				
	seal), running the length of the storage compartment. The Contractor (T. Johnson, JJM)says				
}	that this water is app. 18" deep, and is	normal for an empty "belly dump" barge until the barge			
1		ompletes the seating of the barge bulb seal. The inspector			
		that explanation for the water observed in the storage			
	compartment.				
——————————————————————————————————————	· · · · · · · · · · · · · · · · · · ·				

UR Olevu 1/z4/04 Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

Page 1 of 1

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Safety/Accidents:	
Problems Encountered &	
Resolutions:	
Test Conducted:	KCEL did not test turbidity today as the Contractor started dredging too late in the afternoon.
Work Rejected:	
Instructions Given to	
Contractor & Changes	
Initiated:	
Visitors to Site	
Equipment Used	1
	·





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

[•			
Year	Мо	nth	Day	Ins	pector
2004	1		8		b/KN
!	Ī	Day of the V			
Sat	Sun Mo		Wed	Thu	Fri
				Х	
		Weather	•		
			_		
Clear	PC	Overcast	Fog	3	Rain
			٠		х
		Temperatu	ıre		
10-32	32-55	55-70	— 70-8	5	85+
	X				

Date

Construction Activities:	Crew on site this morning at 4 AM and started dredging at 5 AM. "Crystal Gayle" is filling the				
	barge "Swan Island".				
	Crew continued dredging in Area A, S. of Dredge Plan sta. 1+50. Crew dredging next to				
		ne Area A/B buffer zone. Crew stopped dredging at app.			
		esumed at 11:00AM. Dredging continued with only			
	intermittent stops until the "Swan Isl				
		ninal 25 app. 2:20PM. to pick up the empty barge "Sand			
		I "Sand Island" was moved up to the Dredge at app.			
		ice on the "Crystal Gayle" during the period immediately			
		of the "Sand Is." started app. 5:00PM. Dredging continued			
	with only intermittent stops until 9:0				
	The state of the				
	1				
	1				
	·				
	Dredge- Crystal Gayle	1- Supervisor			
	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
	Barges Sand Island/ Swan Island 2- Survey Crew				
	Survey Boat				
	Crew Boat				
Miscellaneous:					
Safety/Accidents:					
Problems Encountered &					
Resolutions:					

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

Test Conducted:	KC lab on site this morning at 9:20AM to perform turbidity testing at Ebb tide. Flood tide turbidity testing was performed by KCEL between app. 1:30PM and 2:50PM.		
Work Rejected:	***		
Instructions Given to Contractor & Changes Initiated:	Field Office Mtg. 1/7/04 between KC and JJM: The Contractor requested, and has been granted permission to work two eight hour per day shifts. The primary reason for this request is the addition of another Contractor using dock space at Terminal 25 in the near future. Day shift runs from 5:00AM to 2:00PM; Night shift runs between 2:00PM and 9:00PM. The Contractor will work through at least this upcoming Saturday, January 10, 2004 under this two shift agreement. Permission is not granted by KC for any Sunday work.		
Visitors to Site	Bob Parry, USACE; Ukwenga Oleru, KC/PR		
Equipment Used			





KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Mon	th	Day	Ins	spector
2004	1	- 1		9		b/KN
		Da	y of the V	Veek		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						х
			Weather	•		
				_		
Clear	F	PC	Overcast	Fo	g	Rain
			х		_	
		7	<u>remperati</u>	ire		
10-32	30	2-55	55-70	<u></u> 70-1	R5	85+
10-51		X	55-70	70-0		05.
		Λ				

Date

Construction Activities:

Crew started dredging <u>Day Shift</u> at 5:00AM. Crew resumed filling the "Sand Island" that was started Thursday afternoon. Crew stopped dredging at 5:35AM. Crew resumed at 5:52AM Crew stopped at 5:58AM. Crew resumed at 6:07AM. Crew stopped at 6:33AM. Crew resumed at 6:48 AM. Crew stopped at app. 9:25AM. Sand island is full and crew is waiting for the Swan Island to resume dredging. Swan Island on site at 10:13 AM Crew started dredging for the "Swan Island" at 10:23AM. Stopped dredging at 11:22 AM. Started at 11:35 AM. Stopped at 12:08PM. Resumed at 12:19PM.

Night Shift started at 1:00PM. Contractor stopped for maintenance work on the "Crystal Gayle" between app. 3:30PM and 4:15PM. The Contractor continued with only occasional stops until app. 6:20 PM. when the Dredge reached a point near the previously excavated Area A/B buffer zone. The "Swan Island" was approximately 80% filled at that time. The Contractor relocated the "Crystal Gayle" to the Center excavation lane on the Dredge Plan, and resumed dredging at app. 7:08PM from sta 5+00 toward 7+00. At app. 7:30PM the "Norton Bay" left for Terminal 25 to pick up the "Sand Island". Dredge completed working on the "Swan Island" at 8:30PM. The "Norton Bay" returned with the Sand Island at app. that time for the switch.

Dredge- Crystal Gayle

Tug- Norton Bay Tug-Loren M

Barges Sand Island/ Swan Island

Survey Boat Crew Boat 1- Supervisor

3- Dredge Crew

2-Tug crew

2- Survey Crew

UROlevn 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

REPORT NUMBER:

CONTRACT NUMBER: #C33027C

Miscellaneous:	Miller surveyors were on site during Day Shift to map dredging progress to date. JJM Survey crew was back on site at app. 7:00PM to help with the Dredge relocation.		
Safety/Accidents:			
Problems Encountered &			
Resolutions:			
Test Conducted:	KC lab on site at 9:30AM to test for turbidity. Lab had to wait app. I hour to test due to no		
	dredging (barge was full and contractor waiting to change out barge). KCEL on site for afternoon Flood Tide turbidity testing at app. 3:20PM, and were on site until 4:45PM.		
Work Rejected:			
Instructions Given to			
Contractor & Changes			
Initiated:			
Visitors to Site	Colin Wagoner, NOAA Consult.; Len Miller, Rob Matheison, JJM		
Equipment Used			





KING COUNTY

DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

King County Contract No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

<u>Date</u>						
Year	Mo	nth	Day	Ins	pector	
2004	1	!	10	IK	IK/KN	
	Ī	Day of the V	Veek			
Sat	Sun Mo	n Tue	Wed	Thu	Fri	
Х						
		Weather				
Clear	PC	Overcast	Fog		Rain	
		am	pm			
		Temperatu	ıre ·			
10-32	32-55	55-70	70-8	5	85+	
	X					

Construction Activities:	Day Shift: 5:00AM to 1:00PM					
1	Contractor started dredging into the '	'Sand Island" at app. 5:25AM and stopped at app. 6:40AM				
100	to move further S. in the Center Lane	e of Area A (Dredge Plan, sheet C-2). Dredging started				
:25	again at app. 7:05AM and worked ur	ttil app. 8:50AM with only occasional short "penalty				
: 10	stops". Dredge changed location, and	dredged from app. 9:00AM until 9:35AM. Contractor				
:40	stopped to perform routine maintenance until 10:15AM. Dredging resumed and stopped again					
	at 10:35AM for the Contractor to app	at 10:35AM for the Contractor to apparently take measurements. Contractor resumed dredging				
: 25	at 10:50AM and stopped at 11:20AM	I due to Safety concerns about KCEL testing boat (refer				
105	Safety below). Dredging continued a	gain at 11:25AM with only occasional "penalty stops"				
1	until 12:10PM. The Contractor then to	ook a short break to "fox" their lines. Dredging resumed				
10	at 12:20PM, and continued with only	occasional "penalty stops" through the end of this shift.				
	Night Shift: 1:00PM to 9:00PM					
	"Norton Bay" returned and stood by	N. of the dredge with the "Swan Island" after app.				
ļ	1:30PM. Contractor completed loading	ng of the "Sand Island" at app. 2:1.0PM. Barges were				
	swapped at that time. Dredging work	swapped at that time. Dredging work stopped for maintenance at that time. Dredge began				
	filling the "Swan Island" after app. 3:00PM. Dredging stopped again at 3:20PM while the crew					
	worked on a new outboard motor on the work skiff. Dredging resumed after 3:40PM. and					
	continued with only intermittent stops until app. 8:10PM, when the crew decided to stop					
	dredging for the evening.					
	Dredge- Crystal Gayle	1- Supervisor				
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M 2-Tug crew Barges Sand Island/ Swan Island 2- Survey Crew Survey Boat					
	Crew Work Skiff					
Miscellaneous:	Miller surveyors were on site this morning to coordinate dredge movements, and map					
i	progress. Dredging work was inspected this Day Shift with help from Iha Khilfeh, KC/CM.					
Safety/Accidents:	The Contractor stopped dredging from 11:20AM to 11:25AM, due to their concerns that KCEL					
1	boat (conducting turbidity sampling) was operating in a "hot" work zone (within 150' on the					
	<u></u>					

UROleva 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke Construction Inspector (Date)

REPORT NUMBER: CONTRACT NUMBER: #C33027C

	blind side of the dredge boom operator). Craig Chartrand, McAmis Supt., said that a similar incident was also reported by the "Crystal Gayle" operator yesterday afternoon. It was not reported to KC/CM. Craig reported that the dredge operator has made a radio request to the KCEL boat to "stand off", and at least radio the dredge before making moves within the dredge's Work Safety Zone.		
Problems Encountered &	Occasional banks of thick fog rolled into the site from app. 4:40PM until 6:15PM. It became		
Resolutions:	difficult to see the "Crystal Gayle" and dredge bucket clearly (even with binoculars) at times.		
Test Conducted:	KCEL boat on site from 9:45AM to 11:30AM for Ebb Tide turbidity tests. KCEL boat returned to site after 2:30PM for attempt to take Flood Tide turbidity tests (Contractor had many dredging stops within the afternoon test window. Re: Construction Activities Sect. above). KCEL boat left the site at app. 4:15PM.		
Work Rejected:			
Instructions Given to			
Contractor & Changes			
Initiated:			
Visitors to Site	Rob Matheison, JJM (app. 3:00-4:00PM)		
Equipment Used			





DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED


Yea	ır	Mon	th	Day	1n:	spector
200	4	1		11	II.	K/KN
	Day of the Week					
Sat	Sun	Mon	Tue	Wed	Thu	Fri
	X					
			Weather	г		
				-		
Clear	.]	PC	Overcast	Fo	g	Rain
	pm			an	,	
	Temperature					
10-32	2.	2-55	55-70	<u>11-6</u> 70-8	D.E	05:
10-32	. s.		33-70	/0-0	33	85+
		X				

Date

Construction Activities:	Day Shift: 7:00AM to 3:30PM				
	Contractor started dredging for the "Swan Island" at app. 7:30AM. Work started in Area B				
	(Dredge Plan, sheet C-2) to pick up four high spots discovered during a recent survey (by				
	Miller surveyors). Dredging proceeded slowly, with occasional stops (due to the nature of the				
	, , , ,	elocating the "Crystal Gayle") until app. 10:05AM.			
		complete filling the hopper of the "Swan Island".			
		Contractor stopped dredging between 11:10AM and			
		Iging with only occasional "penalty stops" until app.			
		for greasing and bucket maintenance. Dredging resumed at			
		y occasional short "penalty stops" until the "Swan Island"			
	was filled at app. 3:00PM.	,			
	Dredge- Crystal Gayle	1- Supervisor			
•	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
·	Barges Sand Island/ Swan Island	2- Survey Crew			
	Survey Boat				
	Crew Work Skiff				
Miscellaneous:	JJM survey crew were on site this morning at app. 8:45AM to coordinate and confirm the				
	status of dredging performed in Areas A and B. Terminal 25 began unloading the "Sand Island				
	this morning after 11:30AM.				
Safety/Accidents:					
Problems Encountered &	Contractor returned to dredge removal of soils where oil slick had previously developed just				
Resolutions:	W. of an exist. 144" SD outfall. A small amount of new surface oil filming formed, and was				
	minimally contained by the Contractor.				
Test Conducted:	KCEL boat on site from 10:30AM to 11:30AM for attempt to take turbidity tests.				
Work Rejected:					
Instructions Given to					
Contractor & Changes					

UR Olevu 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)



Initiated:		
Visitors to Site	R. Matheison, JJM (8:50AM12:40PM)	
Equipment Used		



REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•					
Year	•	Mo	nth	Day	Ins	spector
2004	ļ	1		12		rb
		D	ay of the V	<u>Veek</u>		
Sat	Sun	Moi	n Tue	Wed	Thu	Fri
		Х				
			Weather	<u>r</u>		
Clear	F	C	Overcast	Fo	g	Rain
			Х			
			Temperati	иге		
10-32	32	2-55	55-70		35	85+
		X				

Date

Construction Activities:	stopped at app. 9:35am for maintena stopped at app. 10:45AM. Crew resumed at app. 10:55AM. Night Shift: "Crystal Gayle" continu from app. Dredge Plan sta. 5+00. Th returned with the "Swan Island", and 1:50PM. Dredging resumed after a sloccasional short stops until app. 5:00	the "Sand Island" this morning at app. 5:10AM. Crew nee. Crew resumed dredging at app. 10:07AM. Crew need excavation from the Center Lane of Area A working S. e "Sand Island" was filled at app. 1:45 PM. "Norton Bay" Itied up on the Starboard side of the dredge at app. nort break period at app. 2:05PM, and continued with only PM, when the crew took a maintenance break. Dredging ued with only occasional short "penalty" stops, or to move then the "Swan Island" was filled.
	Dredge- Crystal Gayle	1- Supervisor
ł	Tug- Norton Bay	3- Dredge Crew
	Tug-Loren M	2-Tug crew
	Barges Sand Island/ Swan Island	2- Survey Crew
	Survey Boat	•
	Crew Boat	
Miscellaneous:		
Safety/Accidents:		
Problems Encountered &		
Resolutions:		
Test Conducted:	KC lab on site at 10:45AM to take tu	rbidity test. No turbidity test was taken by KCEL on Night

UROLEVU 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

REPORT NUMBER: 050 CONTRACT NUMBER: #C83235C

	shift, as the "window" for the testing was well after Sunset (per Jean, KCEL).		
Work Rejected:			
Instructions Given to Contractor & Changes Initiated:			
Visitors to Site	K. Takasaki, USACE; T. Johnson, JJM		
Equipment Used			





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Moi	nth	Day	Ins	spector
2004	1	1		13		b/KN
		<u>D</u>	ay of the	Veek		
Śat	Sun	Moi	n Tue	Wed	Thu	Fri
			X			
			Weathe	<u>r</u>		
				_		
Clear	F	C	Overcas	t Fo	g	Rain
			х			X
			Temperat	ure		
10-32	32	2-55	55-70		85	85+
		X				

<u>Date</u>

Construction Activities:	Day Shift: 5:00AM to 1:00PM				
	"Crystal Gayle" crew started dredging	into the "Sand Island" this morning at app. 5:10AM, in			
	Area A, between Dredge Plan sta. 6+0	Area A, between Dredge Plan sta. 6+00 and previously excavated "buffer zone". Crew stopped			
·	dredging at app. 6:45AM. Crew resumed dredging at app. 7:04AM. Crew stopped at app.				
	9:00AM for maintenance. Crew resur	ned dredging at app. 9:25AM, and continued excavating			
	with only occasional stops until the en	d of this shift at 1:00PM.			
	Miller surveyors on site today mappin	g out dredge area.			
	Night Shift: 1:00PM to 9:00PM				
	Contractor continued dredging work of	on the "Sand Island" until it was filled at app. 1:45PM.			
	"Norton Bay" had already been dispat	ched to Terminal 25 to pick up the "Swan Island". "Swan			
	Island" was tied up on the starboard si	de of the Dredge at 1:50PM, and filling began app.			
	2:15PM. Norton Bay left with the "Sa	nd Island" for Terminal 25 at app. 2:00PM. It returned at			
	app. 3:30PM. Dredging continued unt	il 7:15PM break. Dredging resumed at 7:36PM, and			
	continued with only occasional short s	stops until 9:00PM.			
	Dredge- Crystal Gayle	1- Supervisor			
	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
1	Barges Sand Island/ Swan Island	2- Survey Crew			
	Survey Boat				
	Crew Boat				
Miscellaneous:					
Safety/Accidents:					
Problems Encountered &					
Resolutions:					
Test Conducted:	KCEL on site after 11: AM to take Ebb Tide turbidity tests. Night Shift tests were not taken.				
Work Rejected:					
Instructions Given to		after 11:30AM at the Site Office. The primary items of			
Contractor & Changes	discussion were upcoming capping op	erations and schedule for capping, post-dredge and post-			

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)



Initiated:	cap surveys. JJM also made initial submittal of capping materials and confirmation was requested that capping materials testing was being performed.		
Visitors to Site	Bruce McDonald, AE; Tom Johnson, Rob Matheison, Cameron McIntosh, JJM (left site @1:30PM); Craig Chartrand, McAmis (left site @4:00PM) Ukwenga Oleru, KC/CM; Colin Wagoner (NOAA Consult.), Marla Steinhoff (sp.?), NOAA (2:30-3:30PM).		
Equipment Used			





KING COUNTY DEPT. OF NATURAL RESOURCES

WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Yea	-	Mont	h	Day	In	spector
	•			•		-
2004	1	1		14	r	b/KN
		<u>Da</u>	y of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
				х		
			Weather	-		
			77 0411101	-		
Clear	F	PC .	Overcast	Fo		Rain
Cicas	•	•	Overtast		-	Kam
			X	٠.	•	X
		<u>T</u>	emperati	ıre		
10-32	32	2-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:

Day Shift: 5:00AM to 1:00PM

Crew started dredging this morning at app. 5:12 AM. Crew resumed filling the "Swan Island" which started yesterday afternoon. Crew stopped dredging at app. 6:20AM to turn around "Swan Island" with the bow downstream. Crew resumed dredging at app. 6:50AM, and continued until the "Swan Island" was filled at app. 8:30AM. Crew moved out the "Swan Island" and brought in the "Sand Island" at app. 8:40AM. That barge was tied up on the Starboard side of the Dredge.

Dredge began filling the "Sand Island" at app. 9:03AM. "Crystal Gayle" is dredging in Area A, S. from Dredge Plan sta. 5+90 toward the shore side of base line. Crew moved upstream anchors at app. 9:07AM. Dredging stopped during anchor movement. Dredging resumed at app. 9:14AM. Dredging stopped from app. 9:50AM to app. 10:10AM for maintenance. Dredging stopped at app. 10:42AM to reposition "Crystal Gayle". Dredging resumed at 10:52AM. Dredging stopped at app. 11:35AM to reposition barge. Dredging resumed at app. 11:43AM.

Crew stopped at app. 12:45PM for crew shift change.

Night Shift: 1:00PM to 9:00PM

"Crystal Gayle" upstream anchors were repositioned. "Norton Bay" pulled off the job to run errand for their Company after 1:00PM. Dredging resumed on the "Sand Island" at app. 1:10PM. "Norton Bay" returned to the Dredge at app. 2:49PM. Dredging continued with only occasional short stops until 3:35PM. Contractor took a maintenance break until app. 4:15PM. "Norton Bay" was dispatched to Terminal 25, at approximately that time, to pick up the "Swan Island". Dredging continued until the "Sand Island" was filled at app. 5:35PM. By app. 5:45PM, the "Norton Bay" had brought up the "Swan Island" on the Starboard side of the "Crystal Gayle", and dredging resumed immediately. Dredging stopped at app. 6:30PM and resumed again at app. 6:45PM. Dredging continued with only occasional stops until 9:00PM.

ROberu Proj

1/21/04

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

KING COUNTY DEPT. OF NATURAL RESOURCES WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

(·····			
	Dredge- "Crystal Gayle" Tug- "Norton Bay" Tug- "Loren M" Barges- "Sand Island"/ "Swan Island" Survey Boat Crew Skiff	1- Supervisor 3- Dredge Crew 2-Tug crew 2- Survey Crew	
Miscellaneous:	Miller surveyors on site this morning ma Area A. Craig Chartrand, McAmis, left s	pping and updating information on dredging work in ite at app. 6:21PM.	
Safety/Accidents:			
Problems Encountered &			
Resolutions:			
Test Conducted:	Blue Water Surveyors (Anchor Environmental) on site this morning to survey Area (B) KC lab on site this morning to take turbidity test at Flood Tide. KCEL on site just after noon to test turbidity at Ebb Tide.		
Work Rejected:			
Instructions Given to			
Contractor & Changes			
Initiated:		·	
Visitors to Site	Rob Matheison, JJM(4:40PM-5:25PM)		
Equipment Used			





KING COUNTY DEPT. OF NATURAL RESOURCES

WASTEWATER TREATMENT DIVISION

Inspector's Daily Construction Report

REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Vac	_	Mont	L	D	T	
Yea	-	MODE	1)	Day		spector
200	4	1		15	r	b/KN
		Day	y of the	Week		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
					X	
			Weathe	<u>r</u>		
Clear	·	PC .	Overcas	t Fo	g	Rain
			X			X
		Ţ	emperat	ture		
10-32	-32	2-55	55-70	70-	85	85+
		Χ				
		_				

Date

Construction Activities:	Day Shift: 5:00AM to 1:00PM					
·	Dredging started this morning at app.	5:00AM on the barge "Sand Island". The Contractor is				
	dredging this morning in Dredge Plan Area A, at sta. 7+30(upstream) at the slope area next to					
	shore. Crew stopped dredging at app. 9:20AM for maintenance. Crew resumed dredging at					
	app. 9:50AM. Crew completed filling the "Sand Island" at app.12:30PM. The "Swan Island"					
	is still be offloaded at Terminal 25.					
	Night Shift: 1:00PM to 9:00PM					
		il the "Swan Island" is emptied and delivered to the work				
		e with "Swan Island" at app. 2:35PM. Dredging resumed				
	,	5:45PM to reposition upstream anchors. Dredging				
1		d at 7:00PM, and resumed again at 7:17PM. Dredging				
1	continued with only occasional short	stops until 9:00PM.				
!	Craig Chartrand left the site at app.7:	00PM				
	ending conditional next and sine at app.//.					
	·					
	Dredge- Crystal Gayle	1- Supervisor				
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M	2-Tug crew				
	Barges Sand Island/ Swan Island 2- Survey Crew					
	Survey Boat					
	Crew Skiff					
Miscellaneous:	•	fied by Craig Chartrand, McAmis, about their concerns				
	regarding the results of the turbidity tests of the excessively "soupy" material they were					
	,	cation. The Dredge is currently working the area				
	immediately offshore, and S. of the 1	44" City of Seattle SD in Area A.				
Safety/Accidents:						

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)



Problems Encountered &	On Site Meeting with Wilder: (K. Nordlund present for KC) At app. 3:30PM Steve Perrin and				
Resolutions:	Cato (sp?) form Wilder drove up to Craig Chartrand's Pickup, and hand delivered a rough				
	schedule for upcoming barge unloading at Terminal 25, based on the ability of BNSF to				
	provide trains to handle the spoils. Wilder has basically informed the Contractor that there will				
	not be enough trains available to handle the current schedule for barges being sent to T-25				
	from this site. Ukwenga Oleru was contacted by K. Nordlund about the situation. Craig				
	Chartrand has notified T. Johnston, JJM. Craig Chartrand copied the Wilder schedule, and				
	added dates, etc. A copy of that rough schedule that Craig copied is attached to this report.				
Test Conducted:	KCEL on site at app. 8:51AM to take water turbidity test. KCEL on site at app. 4:00PM to test				
	Ebb Tide turbidity.				
Work Rejected:					
Instructions Given to					
Contractor & Changes					
Initiated:					
Visitors to Site	Ukwenga Oleru, KC; Tom Johnston, JJM; Colin Wagoner, (NOAA Consult.); Marla Steinhoff, NOAA; Cato (?), Steve Perrin, Wilder (3:30PM)				
Equipment Used					
	·				

.]	NEW	SCHEDULE	- OF OF	FLOADING	BARGES
	!]	ER CONST.	•		`
LACOAU	— _С тн		197#	707#	51 27
	FRIDAY	SAT	MON	TUE	WED
	KING CO.	MAUSIN	Marson	KING (O.	MANSON
	2220	23*0	24-4	267	4 /27 **
yn a ddy, han hag, haf ysaffinidhaus, y while allandir ag wefi a	THUR	FRI	SAT	MON	J TUE
	KING CO.	KING CO.	MANSON		
				•	OJEUFD T BARLE
		and the control of th		Fo	
				CRAIG CHI	
	SUB	SMITTED TO X	EUTH (W)	3:45 P.M.	15 JAN 04
			and the second s	and the second second second	
			and the second s	and the second s	
					on any series of the ser
		e i a con case de la constanta de accessorada en la constanta de la constanta			Care Control of Contro
· · · · · · · · · · · · · · · · · · ·					





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

ļ						
ļ						
ŀ						
Year	r	Mon	th	Day	Ins	pector
2004	l	1		16		b/KN
		Da	y of the V	<u>Veek</u>		
Sat	Sun	Mon	Tue	Wed	Thu	Fri
						х
			Weather	r		
			·	_		
Clear	P	C	Overcast	Fo	g	Rain
			·X			
		7	emperati	ıre		
10-32	32	-55	55-70	70-8	35	85+
		X				

Date

Construction Activities:	Day Shift: 5:00AM to 1:00PM					
	Dredging started this morning at approximately 5:00AM. Dredging resumed on the "Sand					
	Island" from yesterday. Area of dredging is in area A. At app. 8:00AM dredge crew started					
	working their way downstream to just outside of Area A. "Crystal Gayle" pulled out of Area A					
	to allow Miller to conduct a complete survey of that area. Crew stopped dredging at app.					
	9:30AM.					
		at the (downstream) NW corner of Area A. Dredging				
·	continued with only occasional stops					
	Night Shift: 1:00PM to 9:00PM					
		casional dredged material onto the "Sand Island" while				
		get unloaded at Terminal 25. "Crystal Gayle" changed				
		OPM. to the outside lane in Area A. Got word from Craig				
		Wilder had informed him that they wouldn't even begin				
		offloading the other barge until 7:00PM tonight.				
	Dredge- Crystal Gayle 1- Supervisor					
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M	2-Tug crew				
	Barges Sand Island/ Swan Island 2- Survey Crew					
	Survey Boat					
	Crew Boat					
Miscellaneous:	Miller surveyors on site at 7:50AM to map out dredged area to date in area A.					
Safety/Accidents:						
Problems Encountered &	One of two torque converters for the Norton Bay's engines is shattered, and McAmis is waiting					
Resolutions:	on a replacement. The problem is severely limiting the Tug's ability to handle the barges. The					

Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

	Tug is also in need of a new starter.			
Test Conducted:	KCEL cancelled turbidity testing today because of the nature of the dredging work.			
Work Rejected:				
Instructions Given to				
Contractor & Changes				
Initiated:				
Visitors to Site				
Equipment Used				





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

	•					
Yea		Mont	ılı.	Den	T	
	-	MON	1.13	Day		pector
200	4	1		17	rt	/KN
		<u>Da</u>	y of the	<u>Week</u>		
Sat	Sun	n Mon T		Wed	Thu	Fri
X						
			Weathe	<u>r</u>		
Clear	ı	PC	Overcas	t Fo	ø	Rain
				- ,	9	
			Х			
		<u>1</u>	emperat	ure		
10-32	32	2-55	55-70	70-8	35	85+
		Х				

Date

Construction Activities:	Day Shift: 5:00AM to 1:00PM				
	On site this morning at app. 5:00AM. The "Sand Island" was substantially completed during				
	Day Shift yesterday, and is still moored alongside "Crystal Gayle" this morning. Dredging was				
	started late this morning due to a major mechanical problem on Dredge. Crew had to				
	replace/repair a deck winch torque con	version (over 3000lbs.)unit.			
	Crew brought up the "Swan Island" at	7:20AM this morning and took the "Sand Island" down			
	to T-25. The "Swan Island" was offloa	nded at T-25 last night.			
	Repairs were completed and dredging	started at 11:35AM in Area A next to channel at app.			
	Dredge Plan station 6+00. Dredging st	opped at 12:10PM for shift crew change.			
	Night Shift: 1:00PM to 9:00PM				
1	Dredging continued moving from N. to	S. toward the Area A "Buffer Zone", in the W.			
		th only occasional short stops until 7:20PM. Contractor			
	resumed dredging at 8:00PM. Dredging	g continued until 9:00PM.			
	Dredge- Crystal Gayle	1- Supervisor			
	Tug- Norton Bay	3- Dredge Crew			
	Tug-Loren M	2-Tug crew			
	Barges Sand Island/ Swan Island	2- Survey Crew			
	Survey Boat				
<u> </u>	Crew Skiff	·			
Miscellaneous:		sisted of completing contour work in areas where Miller			
1	, , , , , , , , , , , , , , , , , , , ,	k is proceeding based on the last complete survey of			
	Area A by Miller Surveyors yesterday (1/16/04). Miller surveyors were on site to track the				
	work again today. Tom Johnston, Miller Proj. Mgr., has informed KC/CM that Miller is "fairly				
	confident" that all contracted dredging at this site will be "complete" by this following				
	Monday, January 19 th .				
Safety/Accidents:	The Contractor did not report any Safe				
Problems Encountered &	Received word from Ukwenga Oleru, l	C/Prep. that Rabanco/Wilder would not have a crew			
		1			

UROLEVU 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke, Construction Inspector (Date)

Page 1 of 2

ll-f, 1/21/04



Resolutions:	available to offload any barges tomorrow (Sunday). Miller is working two shifts tomorrow.			
Test Conducted:	KCEL(Jean, Stephanie) on site after app. 2:00PM to take turbidity tests. Tom Johnston, JJM, delivered two new sample blends of proposed "Habitat Mix", for this KC Contract, to the site office this day for analysis.			
Work Rejected:				
Instructions Given to Contractor & Changes Initiated:				
Visitors to Site	Tom Johnston, JJM			
Equipment Used				





REPORT NUMBER:

KING COUNTY CONTRACT No.: C33027C

CONTRACT TITLE: Duwamish / Diagonal Sed Rem Project

PRIME CONTRACTOR: Miller Contracting

TIME WORK STARTED: TIME WORK STOPPED

Year	r	Moi	nth	Day	Ins	pector
2004	1	1		18		b/KN
		<u>D</u>	ay of the V	Veek		
Sat	Sun	Moi	n Tue	Wed	Thu	Fri
	Χ					
			Weather	<u>r</u>		
Clear	I	C	Overcast	Fo	g	Rain
			Х			X
			Temperati	ure		
10-32	32	2-55	55-70	70-8	85	85+
		X				

Date

onstruction Activities:	Day Shift 5:00AM to 1:00PM					
	Dredging resumed this morning at 5:00AM in Area A. Crew is still filling the "Swan Island"					
	that was started yesterday. Dredging	stopped at 6:25AM to reposition "Crystal Gayle".				
		edge Plan sta. 6+90 (Area A). Dredging stopped at .				
		th and reposition dredge. Dredging resumed at 7:30AM.				
	new dredging location is in Area A in	n the outside (channel) lane. Contractor is working N. to S				
		reas Crew stopped dredging at 11:35AM. Dredge is in				
		channel). Dredging resumed at 11:46AM. Dredging				
	stopped at 12:02PM for maintenance	and shift crew change.				
	Night Shift 1:00PM to 9:00PM					
	Contractor is still filling the "Swan I	sland". Contractor moved the location of the "Crystal				
	Gayle" to Dredge Plan sta. 0+80 in the	ne outside (channel) lane, and switched the "Swan Island"				
	to the Larboard side of the Dredge. D	to the Larboard side of the Dredge. Dredging on Night Shift started at app. 2:25PM, with the				
	work progressing to the S. (upstream). Dredging stopped at app. 2:45PM. Dredging resumed at 3:10PM, and continued with a series of starts, stops and Dredge moves until app. 4:55PM, when the crew took a maintenance break. At app. 5:35PM, "Norton Bay" was dispatched to Terminal 25 to pick up the "Sand Island".					
	Dredging resumed at 5:45 PM with occasional stops until the "Norton Bay" returned. I					
		5PM. Dredging continued with only occasional stops to				
	relocate, until 9:00PM.					
	Dredge- Crystal Gayle	1- Supervisor				
	Tug- Norton Bay	3- Dredge Crew				
	Tug-Loren M	2-Tug crew				
	Barges Sand Island/ Swan Island	2- Survey Crew				
	Survey Boat					
<u></u>	Crew Skiff					
Miscellaneous:	Miller surveyors on site most of this	day, mapping progress in the dredge area.				
Safety/Accidents:	No incidents were reported to KC by					

UR Olleru 1/21/04
Ukwenga Oleru Project Representative (Date)

Randall Brunke Construction Inspector (Date)

Problems Encountered & Resolutions:					
Test Conducted:	KC lab on site this morning at 10:00AM to take water turbidity test. The test that was conducted this morning, Bottom reference (Field) was 1.4 and the 300 feet reading was 48.7. This was 38.3 over. The "Crystal Gayle" was changing location (100 feet +/-) and doing cleanup dredging during testing (not stationary). Testing was actually being performed near the area just recently vacated by the Dredge. This was forwarded by the Contractor as a possible reason for the high readings. Informed Tom Johnson (Miller) of the turbidity readings. Asked T. Johnson if the barge still had filter fabric on drain pipes and he said that they were in place. No change was observed from normal dredging operation (bucket movement/ overfilled bucket). KCEL on site after 3:24PM for turbidity testing.				
Work Rejected:					
Instructions Given to					
Contractor & Changes					
Initiated:					
Visitors to Site	Tom Johnson, JJM				
Equipment Used					